3-24-77 Set CTM

#841506

1/4 Corner 15-16 Oronoco 10 8-14.

1916 Power Dam Survey - Sheet #3060 - show no Corner found (used M+L pt)

No records, no knowledge of any proof large corner post as farm property boundry and that fences south and east are proven correct etc.

10-28-71 required to provide line for road from 9-10-15-16 80 rods south for Oronoco Township. - used corner post as corner (caught heck for trespass) and power pole west as 24° (S) west ran line with section corner north. fence on west side old road uniformly abmt 20' ont. tele pole on west side at

over.

south end of 80 rods. to be 26.4' center west of section line as run for centerroad.

3-24-77 Dug from corner post 3'N, 3'E, 3'W, and 2'S. Found nothing. Set a CIM over a ½" x 2' rod as the corner on the West side of the corner post.

R.P.'s CSD in pp # 37948 WNW 24.18

Cont Notes on back