X 10-20-81 CIM

#851706 (1)

1/4 corner 17-18 New Haven 10 8-15
12-18 73 Hunter P235 no 237 & 17. McDonald & others.
Corner gone, reset stake from stump & NE BT
with marks plain and badly rotted stump & anchor BT.
reset stake from these witnesses.
-16 east set stake M & L 19.83 1/2. (1309.11'
-16 north drone stake M & L 20.00
-16 center NW 1/4 17. drone stake M & L 19.96 on E-W 1/16 line

---

3-1892 2 hos Fraser P471 no 452 & 18 Pat Kennedy. D Kane & others
found boulder. stone - tested by. stump
& NE BT. also SW BT stump - new BT 10" oak. N82 1/2 W 47 1/2 L.

-16 south drove iron stake M & L. 19.94 13/18 (~~1316.3'~~ 1316.52
8" elm. N 76° E 66½ lks (43.9'

Should have been ~~19.94 5/18~~

Co Hwy Dept B 100. 1939. P3.
found recorded boulder 2½' dep. & 2635.6 North 2632.5
Sp oak E 35.0 - Sp 15" oak S E 43.3

12-4-69. road N-S only no fence west found spike in oak stump (very loose, nearly rotted off) set 120 D 2' west & nail to hold R P. no dip in road believe county had true corner. Checked Co Hwy field books. got topo etc B 100

B100 P3 Sta 52+69.4 a P.O.T. near exact fence. east
Topo. corner fence right 29.0 - 52+69, 17x18x17 conc culv. 52+57.
tele pole. beg fence lt. 26' 53+03, 12"x20' culv. 54+05
tele pole. left 26' 52+88

Card # 2 1/4 17-18 New Haven 108-15 (2)

County corner evidently in center road in exact line
fence east - set nail xtee for .00 nail on tie 4 1209
set 2' West of 35.00 nail in stump set by county.
stump gone found 1.20 but instead of 34.56 nail (.00)
would really be 33' #851706

- final meas from iron at 17-18-19-20 to line fence east
2637.0 - 2.7 or 2634.3

final meas from iron at 17-18-19-20 south to C/M at
1/4 19-20 set over iron & stone 2633.45

- final meas from line fence east at 1/4 17-18 north to
C/M at 7-8-17-18 set over W Friend iron and stone.
2632.75 as N-S may as well set midway. 2634.3
or about .75 south of fence east 2632.75
J 546705 (orig)
263352

Corner cannot be set on line if ever used for property survey. OK for road etc. corner would come just about 20' E direct line as Hunter set up S17. 2625.8 S side west 1/2 S17.

2618.2 E-W 1/4 line W 1/2 S17.

2651.2 N side west 1/2 S17. Computed as E-W 1/16 line above or N & center 2634.7

Mean would be 2638.5 or 20' west of record.

- If iron are 17-18-19-20 left at 2635.25 corner would come about 25 feet east of direct line in bottom ditch.
- as lands in S'W 1/4 17 divided at 1/16. N & S, correct corner is important. however S line of W 1/2 S 17 real crazy. ac stone at 1/4 17-20 set. 1873 feet comes 1327' to 1/16 fence north and 1304 from center 17 west. - no proof ac to how main line falls

New Haven 1/4 cor. 17-18
Gen'l Notes Cushing 1954
#851706 13
#6.00 SC & 1/4 SW & post

Sm. Oak 5 in 13 W 82 S
52 E

Oak 5 in 13 S 72 W 59 E

4-15-81 1/16 North: Dug centered 10' East of line between the section corners and in line with the fence East. Area had been entirely cut to clay.

10-20-81 1/4 Cor 17-18: Set a CIM over a 5/8" re-rod at T. Fraser's measure from SW17 and at double the measure the N-S 1/4 line Sec. 17 as computed this survey over the stake found at the 1/16 West. Before setting the corner we dug a 3'x3' hole NW 1/4 of CIM location and found the area cut to sand

subsoil 2' deep. Corner falls 24' East & N-S road &
and 3' South of the fence line East.
RPs C.S Disc in West side pp # 35 SSE 55.46
C.S. Disc in N side c.p. ENE 26.24
Corner 21' N of center of driveway.