April 17-1979 Reset corner with a 3/4" rod M+L
At 2606.30 by electronic traverse #842304

1/4 Corner 23-26 Cronaco 10 S-14.

6-1881 Hunter surv. P123 No 371 old field book for subdivided section 26. set N 1/4 26 at 39.66 (2617.56' M & L. J D Blake. likely stake to locate center 26.

5-1902. W Fraser P18 B S 26. H Fredricks - W Koening. found Hunters records, plat in record book copy of orig Hunter survey - found center 26 - E & S 1/4 cors & SE corner. did not go to or use 1/4 23-26. in river lands, rough wooded etc - river likely west of 1/4 23-26.

- over -

8-27-1941 J Kerr B25 P70 Kolbe-
Meas line between Secs 23 & 26. 4300'+ by triangulation
line a real nightmare 5221'± total. Hunter 5235.12'

April 17-1974 Co Surv.
Set a 3/4" x 3' rod - 3.4' SW of old corner post.
Set the corner midway from line by
electronic traverse — 2606.39 Note: Found mistake in
2606.30 (New comp) trav. comp.

R.P.'s
Spike & C.S. disc in 16" OAK S.S.E. 42.25'
" " 18" OAK (Barb wire around tree) E. 55.37'
Spike & Co. Surv disc in twin 10" OAKS N.E. 26.12'

P.D. Survey (1916) used N-S Fence as Corner
Meas East 2615.0 & west 2604.4

Oromocto 1/4 corner 23-24 #842304 (2)
Gov't Notes M. Kavanagh 1854
40.00 Set temp 1/4 section post
West on true line between sections 23 & 24
40.00 Set 1/4 section post V 9° 18'
Bur Oak 12 N 40 E 322
Bur Oak 10 S 49 E 245