9-14-1963 set C/M ones orig stone & iron (1)
8-30-74 R.R. spikes was other Corner - replaced C.M.D. rod
1/4 corner 4125/90 set 1½" pipe cap in place of RR spike
27-34 Oronoco 108-14.
#842704
6-1884 Hunter P390 No 381 & 27 C R V roman.
Corner gone, dug extensively, enquired for knowledge of corner.
- found 1/16 stone west set by Horton P85 in 1867.
set M & L when all corners were standing.
- reset stake as corner by line & W 27 order 1/16 stone
and doubling distance carefully M & L 19.95. (1316.7
- 1/16 west found stone to line with fences N & S.

3-1896 W Fraser P592 No 538 W½ & 28, E½ & 28.
did not look for corner. & Hall, W V roman.
found & used 1/16 stone west.
- set stake 10.97½. (724.19' then 8.97½ (592.18' to sec cor.

10-1913 D Williams p 240 B & 34. J A Clason.
boulder with post 3' high by it and small stones.
- mens south 2653.3 to center set inters lines.

1911 Power line survey station 39037.5 or 2652.5
south to center 34. & 5219.95 north to N 1/4 27.

9-1963. J Kerr
run aerial line after finding NW cor 34. found 1/4 27-34
to be 8.82' north direct line—
16 west dug in low wet lands for stone found only muck.
set 1/2" x 4' bod. M & L 1315.6. R 1316.35.
Blaze in PP N 27.5 — Center Cor FP & 29.25
very little west of exact south

RP 1/4 27-34. Sp tele pole S E 59.7.
Sp power blaze pole. S W 52.7 — Sp PP N E 50.5
Sp PP N W 39.9. - corner fairly in center crossroads

#842704 (A)

Card # 2 1/4 27-34 Oroco 108-14

8-21-1969 removed C.I.M. set 1/2" rod flush. set 3/4" x 10" rod on hilltop west 6 feet north of mail box standard. this rod lines with west side of main part of house south. Also set 3/4" x 10" rod opposite first power pole. west of 1/4 27-34 247.22' use this ~~246.96~~ 6-12-79 -RProd near ℄ road.

CoHD 1968 B326 found. C/M sta 52+78.52 P.P. NE 50.5 spk in T.P. SE 59.7'
Meas south 2651.6' spk in Meas north 2601.62
spk & disc in P.P. NW 39.9' spk & disc in brace pole SW 52.7'

June, 1867 H.E. Horton Pg. 85 No. 131 Shows 1/4 Cor. used to break down, N.W. 1/4 sec. 34 1/16 West 19.94 1/2 m/L to Sec. Cor.

7-6-1970 C.H.D. ties after grading
Set a 3/4" rod

Sp. - disc. in P.P	N.W.	56.32
Sp - disc in brace pole	S.W.	65.52
Sp - disc in P pole	N.E	54.46

8-28-1974.
Reran the North line sec 34. - Set the Corner 8.82' N. of the line between the Sec Cor. as J. Kerr. refered to when he had the stone. For E.-W control we used the rod 249.22' West. this moved the C.H.D rod .28' E. We also reran the N-S 1/4 line Sec 34. & this line fell on our New point at the N 1/4 cor 34. Set a R.R. spike for the corner.
N 1/4 cor 34 E. = 2642.27.
W 1/2 = 2632.14.

R.P.'s

C.H.D disc N.E. side of P.P. # 41290	N.W.	56.44.
" " N side of P.P.# 36675	S.W.	65.89
C.J.D. S.E. side of PP # 41074	N.E.	54.08

Oronoco 1/4 corner 27-34 #842704 (3)
Gov't Notes M.T. Kanick 1854
40.00 Set stamp 1/4 Sect. post
West on true line between sects 27-34 V 8°47'
40.00 Set 1/4 section post on mound, w. 4 bearing pits, charred stake + Osage Orange stobs
W. E. + S. W.

1/4 27,34 4/6/90 DUG UP R.R SPIKE SET (1974)
IT WAS 5" DEEP IN NEW MAT OF Co. Rd. # 112
THE POLES IN SW & NW CORNERS OF INTERSECTION
OF C.R. # 112 & C.R. # 154 ARE NOT THE SAME
POLES AS (1974) TOOK NEW RP's
CSD IN P.P. # 43191 NW 66.54
CSD IN P.P. # 50637 SW 68.50
CSD IN P.P. # 41074 NE 54.30
4/25/90 SET 1" SQ PIPE/CAP IN PLACE OF R.R. SPIKE