#842705

9-22-1966. set C/M over. 3/4" x 2' pipe in small rocks.
9-27-77 Set CTH
section corner. 27-28-33-34 Oronoco 108-14
6-1884 Hunter P 390 no 381 S 27. C R Vroman. (1)
found stone in center road set by Mr. Vroman.
and others interested in mound when corner stood.
-16 east found stone M & L 19.95 set by Horton 1868.

3-1896 2nd Fraser P 592 no 538 W 1/2 S 27, E 1/2 S 28.
found stone corner P 390. S Hall, W Vroman.
-16 east found corner M & L 19.95 P 390.
-16 west set corner M & L 19.93 1/2. (1315.7'
- east set prop corner stake at 8.97 1/4 (592.18
then 10.97 1/4 (724.19' to 1/16 stone.

-over-

10-1913 D Williams P240 B L34 J A Clason.
found. 2 stones in south wheel track accepted as corner.
RP's set – Cottonwood LW 57.4' walnut LE 48'
– meas south to point set M & L for line E 2637.6

9-1966. J Kerr:
found enormous cottonwood & too small walnut wound & stunted by wire, likely B trees P240.
– meas line from west & prop line east, dug extensively finally found stake with 2 stones & smaller rocks.
set C & M over 3/4" x 2' pipe, stones glass etc.
– corner lies ~~5 N 60° E 44'~~ E – W road ~~travel~~ surface.
– 20 D south side 48" cottonwood. AZ 233.15 LW 58.7.
– " east side 18" walnut AZ 134°45 LE 48.0.
– disc NE side power pole with trans AZ 303°45 NW 39.0'.
on looking south the east end of large steel Quonset shed. 400' ± seems to line exactly with corner.
– 16 east set rod M & L 1315.6. see 1/4 34-27 – meas L. 2638.6 M & L.

#842705 (2)

Card # 2 27-28-33-34 Drawer 108-14.

5-10-1972 Co surv. removed C/M & reset with ½" iron rod over iron below. - all RPs will be destroyed in grading. Cottonwood already blown down in 1971 storm. set transit on corner two azimuth on Tower in distance L 46° 50 from E or AZ 136° 50' — 100.0' S.E. To rod - set 5/8" x 2' rod in sheep pasture which lies about 42' South of Sec line ±

8-29-1974 Co. Surv. fd - 60p spk probably set by Co. H.D. checked R.P.'s and ~~Correct~~ set spk Correct - used corner To check location of ¼ Cor. 27-34

June, 1867 H.E. Horton Fd. Bk. 85 No. 131 shows 3 sec. cor. used for break down of N.E. ¼ sec 33 & N.W. ¼ Sec. 34, 1/16 East 19.94 ½ chs M&L

9-29-77 Found nail used in 1974 badly bent so dug down to Kerie pipe. Set CIM on pipe. ½" rod set in 1972 found badly bent so removed it. Corner in ℄ E-W road and in line with East end of Quonset to Soutz.

RPs: ⅝"x 2' rod set in pasture SE 99.92 (rod approx 46° 50' So of Center of road East and on line to 1972 ← tree in distance)

OK 5-31-81 but line came .07 E'ly

Sp & CSD in W side 24" Maple N 79.09 OK 5-31-81

CSD on SE side of brace post on W. side of driveway N NE 96.46 96.44 5-31-81

Sp & CSD in NE side 18" Walnut SE 48.01 48.03 5-31-81

Corner in ℄ E-W road and in line with East end of Quonset to South.

#842705 (3)

Section Corner 27-28-33-34 Chronos 108-14

5-29-1981 - Sec. Cor 27-28-33-34 : Found C.I.M. tilted West, Dug out the C.I.M. and dug down to Kerr pipe. Reset CIM over pipe and re-read ties.

RP: 5/8" x 2' rod in pasture SE 99.92 (projecting line from radio tower over the mtn would throw corner. 07E

- Spike & C.S.D. in W. side 24" Maple N79.09
- C.S. Disc on SE side of brace post on West side of driveway North NE 96.44
- Spike & C.S.D. in NE side 18" Walnut SE 48.03

#842705 (4)

Card to follow 27-28-33-34 Oronoco

1/16 corners and property corners on section line between 1/4 28-33 and 1/4 27-34 Oronoco

-10-1969 set 1/2"x2' rod between 1/4 28-33 and 27-28-33-34 total 2623.64. R 2631.42

corner altho short came in line fence north and line north corrected came just east of old fence. proving corner. - rod near north edge road, 6' + north center pavement road pepsi cap in power pole * 36653 NW. 57.3

SE corner concrete corner post (by +) SW 48.8

angle of 1/16 line north corrected to S line S 28 west 90°19' corner M&L 1311.82.

over

1/16 corner S 1/4 27. and S ¼ cor 28. rod set 1967.
M&L 1315.6. ½ x 4' rod. Disc PP N 27.5 –
Center cone corner post & fence (a little west of south) 29.25'
– 10-1969 found meas west as 1316.1. R 1316.7
set prop corner on line at 592.25 R 592.51 from
SW corner 27 east. then 723.85 east to 1/16 above.
RP to prop corner. – iron 33' north on angle of 1/16 east-north.
orange cap in power pole. 39594. NW 39.75.
Good relocation of Kerwick-Bell
80.00 set a post for corner to sections
27-28-33-34 Erected mound with branch,
pointing chained stake, & Orange Orange
stakes at each angle

Sec Cor 27-28-33-34 108-14 Oronoco #842705 (5)

6-4-98

found (CIM) in ℄ CR# 154 fd (Sta Landfill - 1" square pipe w/cap on South back slope CR# 154, will use as Ref before Cold recycling project

Note: (CIM 25" deep under new grade)

π @ Ref pipe (Landfill)

2 Rt PK Nail in PP # F14-28-1.0-18.0 (Pole Northof Ref pipe) to Sec Cor 27-28-33-34

π = 299° 45' 34"

Hor = 90.645

T= 50°
P= 29.0 "842705" I 6-4-98
MW EA MC 47

✓Sec Cor. 27-28-33-34 108-14
Found (CIM) in ℄ CR#154
fd (Sta. Landfill - 1" square pipe
w/Cap on South back slope
CR # 154, will use as Ref
before Cold recycling project.
Note: (CIM 25" deep under new grade)
TO Ref Pipe (Landfill)
&RT P.K. Nail in PP# F14-28-1.0-180
(Pole North of Ref pipe) to
Sec Cor 27-28-33-34

299° 58' 59" dh 00 302° 06' 33" dh 00
0° 13' 23" dh 01 2° 21' 01" dh 03
299° 45' 36" 299° 45' 32"

To Sec Cor 27-28-33-34
VA 90° 45' 16" dv 03
slope 90.655 Hor 90.645

"842705" SEC COR 27-28-33-34 108-14 6-D-99
EA NC MK
SET 1" SA PIPE W/CAP AT SURFACE FROM
1998 REF PIPE. CORNER FALLS IN ℄ DR 154
+92½' W OF ℄ FIELD DR NORTH.
CSD IN PP NE 93.72'