5-1-1964 set C/M over ½"x 3' pipe mold stake

¼ corner 6-22-61 Set 1" sq iron. Center 27 Computed 8-22-61 to ground Oronoco 108-14. Holes (1)

6-1884 Hunter P 390 No 381 S 27 C R V Roman.

#842709

set stake at true inters lines.

-16 west set stake M & L 19.86. (1310.76'

3-1896 W Fraser P 592 No 538 W½ S 27 E½ S 28.

found corner set P 390 S Hall - W. Roman.

-16 west found stake P 390 M & L 19.87½. (1311.75'

set stone in place of stake.

- west also set stake 10.93½. (721.7' west above ¼ Cor.

1952 McGhie set rod - assumed.

true corner later found 1.95' west and .5' south above.

- over -

5-1967 J Kerr. B93 P32.
run N-S 1/4 line - set E 1/4 cor M & L.
dug 3' x 6' to clay and water. found old stake remains
with large harrow tooth driven by its side. went west
found stone not quite vertical by corner 1/16 fence South
and east. reset stone with angle iron near by just
west of 1/16 corner past of fenced east & south.
- set C I M corner 1/2" x 3' pipe driven down thru stake.
as set, corner lies 1.15' south of direct line of 1/16 sline
and E 1/4 as set M & L. proving E 1/4 cor.) also .45' east of
direct line N & S 1/4 corners proving both of them.
- ~~govt Geo bench mark center Δ~~ NW 36.4. moved in 1970
- disc in PP SW 36.4 — disc in PP SE 43.1.
- nail in tele pole with outlet bell NE 44.3.
- corner lies exact center road east - 3' west center N-S road.
property corners rods set east 1164.5 and 1884.8 both in S
road ditch.- Power dam station 4 1 6 5 7 Geo marker.

#842709 (2)

Card no 2 Center 27 Aronoco 108-14
8-21-1969 removed C/M set 1/2" rod flush.
~~Federal Geo. Marker~~ NW 36.4 moved 1970
set rod. WNW at 70' then at 150' (from corner)
the 150' rod lies 10' north of rather poor fence E & W.
70' rod lies 4 inches north of Tiny pine tree 10" high.
150' rod lies 8 inches east of 1" walnut tree 5' high ±.

Co H D B 326 1968 set 60D by RPs. Sta 78+80.14
could be .6' less.
Meas South ∠ 60D 2601.62.
Meas North ∠ 60D 2619.65 to C/M

L.S. 59

6-22-81, Center Sec. 27: Looked in woods for John Kerr 1969 reference irons & found them in good condition. The 70' tri fit. The line came .09 North of the replace iron. Dug limit the jackhammer and the backhoe. We found 2 1/2" irons at various levels as we went down. We found the 1/2" pipe that was below the CIM which J. Kerr pulled in 1969. This pipe came .04 North of replace iron. Set a 1" square pipe with Cap# 8952 at location of Kerr's pipe. The corner falls in ℄ of N-S road & in ℄ road East.

RP's

C.H.D. disc in Telephone pole NE 63.59
C.H.D. disc in pp # 41075 SE 52.00
C&D in pp # 43200 WSW 51.99

LRP Replace Iron } N 2.22 E 1.50 1/2" pipe N 2.18 E 1.50

6-1961 Found small limestone standing .56 So and .05 West of pipe at property corner West of 1/16 W. Set 1" sq pipe with cap and tag above soil