6-8-1964 set C/M over 5/8" x 2' rod. #842805 (1)
4-26-72 found orig stone - removed C/M. set conduit pipe.
section corner 28-29-32-33 Oronoco 108-14
4-29-77 C/M
5-1873 Hunter P224 No 227 S 32. R Williams, A Hannon.
found stub of stake in center road, avered by A Hannon
and others to be where orig corner stood. (corner likely
- set 2 stones 2x6x15 side by side. used P249 No 250
- 16 south set stake midway only 19.97. 1318.02 te meas west 39.80
- meas west to long granite boulder. 39.80 2626.18

11-1912 D Williams P186B NE 1/4 S 32, NW 1/4 S 33, Reter
found 2 limestones side by side with stake between on
south side center of road.
RP 34 1/2' straight north to nail in bottom [redacted] maple tree.
-16 east corner shown M&L 1313.4 or 1313 ft Hed to road.
- over -

corner found and used many years replaced with 3"x 20" cast pipe outside 3/8" x 36" pipe.

8-1964. set CIM over 5/8"x 2' pipe in place of corner.

- steel fence post with iron braces S 28.58.
- spud. power pole. SSW 106.6.
- " " " SSE 99.6.
- MHD disc, harrow tooth in 20" maple N 34.63

(pera. note corner well vouched for but suspect corner would fit all mear east ~~[redacted]~~ better if further west 6'± & south 3' no stones now.

- Mear west to M&L (yet to be set) 1968 2628.65 R 2626.8 1873
- Mear east to CIM set M&L. 2624.05 R 2626.8 1913
- 16 south found spot of corner set 1913 B96 P63 10-1967. about 1.5' of stake 2.5' west of corner fence N & E at 1317.3 from N. R 1318.02

#842805 (2)

Card # 2. 28-29-32-33 Oroville 108-14.

4-26-1972. Co surv. dug with tractor for recorded stones found exact recorded limestones 2x6x15 with very old stake between. which came 2.0' west and 0.3' south of C/M. removed C/M and rod below and set 3/4"x2' thin wall conduit between stones in old stake remains. removed C/M & rod below completely.

- road due for extensive county grading so made extensive RPs

150.45 N N W To Center 3" Round REA corner post SW. corner.

132.8 N N W " N.E. Corner.

50.4 S S E To head of bench nail on N side large PP.

35.04 N to hub and head of drag both E side maple gone stump.

47.58 NE to hub and nail on SE side stump — gone

52.0 NW to nail hub on SW side corner post

(over

4-28-72 found undisputed corner stone at 1/4 32-33 likely set by Williams 11-1912 P186B. - did not check N both set CIM at 1/4 32-33. checked line over 1/16 west and center 32 to CIM at 1/4 31-32 all within tenths of direct line - dug twice for 1/4 28-33 way south of CIM as set found nothing but good evidence by road that corner could be there.

9-29-77 Set CIM over 5/8"x14" rod appx .06 E of rod(removed) probably set by CHD. Only two old RP's remained: The SW corner of the substation and the NE corner of the substation. Corner in ℄ of E-W road.
believe CHD used slope measurements.
New RP's :. NE side of SE corner of substation NW94.81
Punch mark in top lug at E end CMP in driving So. SW 78.31

Section Cor. 28-29-32-33 Oronoco 108-14 (3)
Gov't Notes: M. Karrick 1854 #842805
80.00 set Post for Corner to sections. Erected Mound with trench, Pitts, Chared stake, and osage orange Seeds at each angle,
6-4-98
Fd CIM at Surface of CR# 154 in good condition
Set Ref pipe w/cap NW of Corner near people Coop Oronoco Substation
π @ Ref pipe
∡ Rt PK Nail in PP# F14-28-1.0-1.0 (2nd pole Easton No Side CR 154 to Sec Cor 28-29-32-33)
∡ = 38°38'18" Hor = 78.64

"842805" F 6-4-98
MW EA MC 49

√Sec Cor 28-29-32-33 108-14
Found CIM at surface of
CR# 154 in good Condition

Set Ref pipe w/Cap NW of
Corner near People Coop ORONoco
Sub Station

T@ Ref pipe
&RT P.K. Nail in PP# F14-28-1.0-1.0
(2nd pole East on No. side CR154
to Sec Cor 28-29-32-33

38° 41' 26" dh 01 40° 10' 58" dh 03
0° 03' 10" dh 00 1° 32' 37" dh 00
38° 38' 16" 38° 39' 21"

To Sec Cor 28-29-32-33
VA 90° 44' 41" dv 07
Slope 78.645 Hor 78.64

74

6-10-99
ETA MC MR

"842805" SEC COR 28-29-32-33 108-14
FOUND PK NAIL SET BY SURVEY CREW @
SURFACE. SET 1" SP PIPE W/CAP AS FINAL
CORNER CORNER FALLS 1' S OF ℄ CR 154 +
23½' E OF ℄ RYAN WINDOWS + SIDING DRIVEWAY S.
CSD IN PP# No # N 54.47'