Corner Corrected 4-11-1975 Set C.I. Mon rod M&L

~~4-6-1964 set C/M over. 3/4" rod.~~ #843006 (1)

1/4 Corner. west 1/4 30 Oronoco 108-14.

east 1/4 25 New Haven 108-15

2-1882 Hunter P374 No 365 S25 Self Wilson C Vroman.

stake missing, B trees entirely gone. found stone set as corner in center road claimed set where orig corner stood corner undisputed used & left as found

---

10-1890 Thos Fraser P446 No 431 S25. Moulton, Back, Perkins stone unrecorded set by Perry, evidently found P374 gone. Run & meas east sec. line 25 short 64 1/2 lks. (5237.43)

- set stone 8"x14" pointed boulder. which came 5 feet south of fence west.

- west set prop. cor stake 22.50 (90 rods for line north

-over-

6-1899 R Fraser P642 no 578 S 30 ch Stevens
found boulder 3' east ridge & road running north.
drove iron stake by side of boulder
B.T. Br Oak N 51° E 56 lks - 8½ paces east of west
road fence running N & S.
- south set prop. Cor. at 14.87 7/16 (981.7'.
then 24.79 7/16 (1636.2' To SW cor 30-39.66½ or 2617.9'

6-1899 R Fraser. P643 no 579 S 25 C Storms Holmes & others.
found corner P642. - meas south 39.66½ (2617.9.
-16 west set stake M & L 19.92½ (1315.05'

---

found corner pipe & ½" rod. set C/M over ¾" rod.
Lp tele pole. NE 57.2 — Lp 20" maple NW 43.8
fence line west. S. 6.4 - Center 24" Oak ENE 125.0
pipe at meander line survey. 1942 B27 P13.
Natural lightning blaze.

#843006 (2)

W 1/4 30 P 446 10-1890 Thos Fraser. Owner

There was a stone here spoken of by R Perry in survey of section 31 above spoken of. but it set on a nob in the road and had been plowed out & there was no evidence of it or where it exactly stood. so the only thing would be to run it in. ran line from D to A N 10° E set stakes at 40 and 60 chs from D. corrected 5247.43 to H. with 32 1/4 chs 21.28' as A to D was short 26 48.71 64 1/2 chs 42.57' - this placed it about 4 or 5' south of a fence running west set stone 17"x8" running to a point on top, a boulder.

Robert found boulder stone about 3.1 E of road running N on W edge of ridge. drove iron stake by side of boulder. 2617.89 P612 2617.89 P613

Meas D 14.87 1/2 981.7 chs 29.79. 1636.14 over

W 19-30 Corner P446 Thos Frazer

There was a corner post set here and fences running S-E-W and had been used as the corner, I searched for witness trees but they were all cut but found stumps of S E and N W witness trees which agreed in distance very close in course with the post and from this found remains of other 2 stumps S W and S E but completely rotted away but answering close in size. there were marks on the stumps on account of being rotted they were only poplars we took the post as the corner and drove a stake marked as N E scribe Rabb Informer survey a post here was given and stake beside it we found the post and stake and also found the hole of a staff south of stake I think was post stake no less

Card # 3 West 1/4 30 Oronoco 108-14
East 1/4 25 New Haven 108-15 #843006

3

5-3-1973 Meas from C/M west roughly.
R. 10-1890 J Fraser 22.50 chs. 1485.0 alt within 2'±
Meas south to fence line each
R. 6-1899. P642. 14.87 7/16 (981.7 alt ±with 300' about 985±
dug massive area with tractor carefully. some medium
boulders in fill road really had rough time - quite dry.
found possible hole where a wood stake had been. didn't
look like hole of iron stake
hole came. 4.25 south and very little east .05 or less
from C/M in place. drove 1/2" rod left C/M as is.
until line can be electro meas with accurate line
put old TV channel in hole with bottle neck in stake hole.

OVER

~~RP 1/2" rod temp corner at W'4 30~~ 1975 R.P.S
CIM
~~30.22~~ 30.48' W to pepsi cap on S side corner post

~~53.83 ESE to punch hole S end 18" Culv.~~ Buried in snow 4-1975

~~136.5 NNW to L mark .38 N of S end 15" Concrete driveway culvert.~~

2.0 + SN to eye line fence west.

NE 131.23' S.E Corner 4" telephone box

NW 97.79' C.S.O S.W side power pole #23977

SW 77.66' Spike on S. side 10" Walnut

4-11-1975 Set C.I.M over 5/8" x 10" rod at 2617.93 M&L

Corner comes 5.22 south and .2± east of Iten's corner and .23' east and .96' south from stake hole