X

#843404 (1)

1/4 Corner south 1/4 34 Oronoco 108-14
north 1/4 3 Cascade 107-14

2-1889 Hunter P427 no 415 L3 J Clason, C Oswald.
shellrock at surface in road, corner gone. set temp
point by meas only 39.90 from NE corner 3 for line L.

10-1913 D Williams P240 B L34 J.A Clason.
corner in rock. gone. run line L E 34 west 2 miles
2637.8 for each half mile. drilled hole in ledge rock.
as corner, put wood plug in it with tin & stones about it.
-16 each set sandstone M&L. 1318.9' and coal.
- meas north 2628.3' to stone set inters lines.

-over

Co Hwy Dept. & J Kerr.
Iron pipe set as corner.
Sp in P Pole. NW 53.55 – Sp in tele pole. SE 47.76.
" " " SW 62.0. – " " F corner NE 47.5

Co Hwy Dept. 1965 RPs 3/4" iron bar. Book 310
Sp tele pole SE 48.09. – Sp Elec power pole. NW 62.46
" P P pole. NE 49.52 " tele pole SW 46.55
8-21-69 repair cap in PP#36221 ESE 122.0
Meas west 2637.8. Meas east 2636.7

1938 Co HD B95 P6. Iron bar. Sta 727+11.2 .00 L 52.
Sp P P NW 92.5 – Hut NE 100.0
Sp tele P SW 40.1 – Sp T P SE 51.3
Meas. west 2637.2 To L. 33-34

1968 Co HD B337. found 1/2" rod as 1/16 corner betw N1/2 3 and center 3. a P.O.T. on new road alignment. RPs to 1/16
Sp A FP NW 44.85, Sp A PP Sd W. 93.52
Meas north from 1/4 cor to center 3 4 2626.91

1973 A2628.3

#843404 (2)

Card # 2. south 1/4 34 Aroneo 10 S-14.
North 1/4 3 Cascade 10 T-14

8-22-1969. J Kerr. found corner iron in black top P.K.
2 new RPS - had dec in power pole SE 122.0
" " NW 62.46

4-24-1979 (1979 Remon. Page 41) Shot 5/8" iron fd here.

(1991) C.H.D Set 1" sq pipe w/cap referenced PK nail in P.P.
± 350' South of PI on west side of CR112. Turned 4 Rt
124° 12' 19" for a dist of 49.39 to 5/8" rerod (corner)

6-11-93 Set 1" sq pipe w/cap as corner. The corner falls
in ℄ E-W CR#14 ± in ℄ CR#112 N ± S.