9-15-1963 set C I M over recorded boulder. (1)
Aug 20 1974 set R.R. spike in blacktop. Cert 4-18-75
1/4 Corner. Center 34 Aronoco 108-14.
#843409
10-1913 D Williams P240 B S.H. J A Clason.
set stone at intersections after finding or setting
all 1/4 corners. stone as set came 6 south of east
west fence lines.
- meas west to corner set M & L. 2636.8.
- meas east 2641.4. To corner not described.
- meas south 2628.3 To corner set (hole in ledge of stone
- meas north 2653.3 To corner found not described.
- 16 east set corner M & L. 1320.7. which came under
E-W fence 25.5' east of 1/16 fence running north.

June, 1867 H.E. Horton Bk. 85 No. 131 Shows Center Sec.
used to breakdown N.W. 1/4 Sec 34
1/16 West 19.93 Chs. M&L to 1/4 Cor 33-34 - over -

- corner Center 34 is a greenish boulder found and used in surveys. with pipe placed as riser.
9-1963 set C/M over orig boulder.
which came 6' south of fence east as recorded.
- ~~ground wire on power pole.~~ gone SSE 91.25'
- ~~splice on spread wire on power pole~~ SE 190.75'
- Center clump cedars WNW 112.0.
9-21-66 B 94 P 65
- 1/16 west set rod M&L. 1316.45 for line north.
this corner lies 2.7' west and 4.1' south existing fences
- 16 Center NW 1/4 34 set 120 D on line at 1320.1 from.
1/16 corner north - comes 1' west of 1st steel post south
of field fence running east (stoned go 2.72' south for M&L
- meas south 2629.45 R2628.3 - north 2652.5 R2653.3
- meas west 2632.9 R2636.8
run line east to help set 1/4 34-35 no accurate line (Must re-run.

#843409 (2)

Card # 2. Center 34 Aronoco 108-14

re-tie ℄ corner after removal ℄ C/M. set 1/2" rod. for grading R.P. 1/2" rod west 3' south Cedar clump. 112.0'

NE corner. Conc block foundation attached garage. NW 130.55' 130.74

Co H.D. 1968 B 326. found C/M. 8-21-69. Sta. 26+28.91 with ℄ 1/4 34 as 0+00 cor. ℄ P.I. no angle Hub NE ~~for~~ 37.44, ~~℄ D Cor Gone~~ E 33.67, ~~℄ D Gone SE~~ 9.29

Meas north 2651.61

4-26-72 C surv. found 3/4" iron set by Co H.D. which came about .1' too far S for NW R.P. and was proven so by finding 1/16 stone set by D Williams (with cross) .1' N ℄ line over

found 1/16 stone at 1321.16. R 1320.7, about 1' west of new concreted iron corner post. also remains of old corner post. 25.5 west proving 1/16 and also W 1/4 3 4 as set. - road unsurface - no C I M til later.

8-29-1974 Co. Surv. - found 3/4" rod set by Co. H. D. in ℄ Co. Rd #112 at surface of Blacktop

Checked R.P.'s Spk in P. Pole - N.E. 67.66

S.E. Cor. of House (Bot of Siding - up 3') - N.W. - 104.0

N.E. Cor. Conc. Blk. Fdtn attached Garage - N.W. - 130.8

1/2" rod - (up 2") 3' So. of Cedar Chimp - W.N.W. - 112.07

8-30 1974

Reset a R.R. spike exactly at intersecting lines & the above R.P.'s are corrected to the R.R. spike set at intersecting lines

4/6/90 DUG UP R.R. SPIKE SET 1974 @ INT LINES IT WAS DOWN 4" IN NEW MAT OF C.R. # 112