4-26-72 set final corner. 1" pennfrod. - removed 1966 corner
6-12-79 Reset c.i.m. over ½" x 2' rod
#843506 (1)

¼ corner 34-35 Oronoco 108-14.

to- 1913 D Williams P240B & 34. J A Clason.

Corner used to set center 34 and 1/16 corner west.

no desc. of corner but assumed to be stone.

- meas west to center set inters lines 2641.4.6
- meas from center west to W ¼ 34 set 2638.8
- 16 west set corner at 1320.7. which came under E-W fence. and 25.5' east of fence north.
- total mile E-W ¼ line 5278.2
- total mile N-S ¼ line at center. 5281.6. or. 2628.3 south and 2653.3 north.

-over-

8-1960 J Kerr B 80 P46 established corner by using true center S 34 and aerial line of fence west which later proved way south of line.

9-1966. J Kerr Book 94 Page 65
- run west line S 34. set W 1/4 34. way north of fence.
- also checked meas of center to N 1/4 34. 2652.0 R 2653.3.
- meas SE 34 to NE 34 5264.2.
present RPs spike PP SSW. 36.0.
60 D NW side 40" maple. NNE 60.0
- corner lies way north of fence west which proves wrong as W 1/4 34 as set lies 9.3 north of E-W fence
- school #129 Book 31 P370 of records 7-1870. 8 rods (132') square - SW corner school 44 rods (726') N. from above corner - (this corner definately wrong.

See Card # 2

Card # 2. 1/4 34-35 Oronoco 108-14 #843506 (2)

4-26-72 Co surv. decided to set or find final corner knowing J Kerr corner set 8-1960 in grass error B80 P46.
- offset 20' south at 1/16 iron west of Center 34 set on line to 1/4 33-34 set later on notes of D Williams 9-1966 B94 P65
- offset 20' south at iron found at Center 34 set by Co & D which came .1' ± south of RPS
- proj. line east and found recorded 1/16 stone with cross set by D Williams 10-1913 P240 B at 1321.16 R 1320.7
- const line east on new offset 45.28 north of offset.
- found J Kerr 1" iron - dug where corner would come found old road gone to alley
- reset iron removed at 1321.16 from cross on 1/16 stone and at correct mean south - may set CIM later road over) grade not so hot but may not be graded out

34.06 W To orig spud in S side PP 33632 ag 2' orig 36.0

43.3 NNE to lead of 60 D near ground ones on W side huge maple set new 20 D ones. nail

27.95 — chisel mark K P 1914 — 1 cross cut of 29.95 but 27.95

29.95 just N & E to hard nails in knot on S side tele pole.

71.0 ENE To center 7" pine (scar on N side near base).

— Hyhurn meas from J Kerr corner N to SW cor school lot.

new corner 16.3 south and 2.8' east of J Kerr corner

in center road on near track line fence meet.

Power Dam survey (1916) Stone found. Meas. South 2628.0

Oconee 1/4 corner 34-35 #843506 3

40.00 Set 1/4 section post in mound with branch, pits, charcoal stake and Orange Orange Seeds at each angle