X

#843604

1/4 corner south 1/4 36 Oronoco 108-14.
North 1/4 1 Cascade 107-14.

4-1875 Hunter P 270 no 268 Ll. A Coveiche.
corner gone, reset corner from ✱ E B T and stump
N E B T.

-16 south set stake on line at 19.52 chen 19.88
to center Ll = -found old stake after running line set
survey no 77. one link north set new stake for line W.

8-1938 Co. H.O. (J. Kerr) Co. H.D. Book 95 p. 2
Set Hub @ N 1/4 1 Sta. 26+18.8 from Twp Cor. as set (wrong found cor. now 1976)
R.P. 8" Oak S.E. 70.7 — 8" Oak NE - 67.7 (82.25 later)
(W. 2620.03 later) (E. 2618.97 later in 1938)

-over-

~~to Hwy Dept~~ McdB data March 1959

Set 5/8" rod in black top

Sp	S side	power pole	E. & E	102.25
"	W "	12" oak	& E	70.5
"	W "	8" "	&	68.2
"	W "	8" ash	NW	78.3
			E	227.0
Steel bridge			N	3.65
Center line road				

1965 RPS & drag tooth in road. B310. Meas east 2619.63

Hub North 39.92.

Sp power pole E. & E 102.17 Meas west 2619.61

Dia 3.78 south of center line

Power Dam Survey (1916) Found stake Meas West 2626.6 East 2622.9

#843604 (2)

¼Cor S. ¼ 36 Oronoco — 108-14
N. ¼ 1 Cascade — 107-14

8-6-1979 Co. Surveyor - dug for original Corner or T.H. Corner with a dozer ~~from~~ off To a depth of about 2 feet from present road which is being regraded. Road fill was down on sandy/Gravelly Surface and obviously Cut from orig. ground level. Did noT find anything except old Tree roots in one area near where corner could have stood. (over)

dug hole 40' long E-W centering on spot produced from 1/16 Cor. South & S. 1/4 Cor. and 10' N & S of ℄ Existing road.

4-18-1979 16th South (1979 Remon. Book Page 29)
found a ½" iron by the corner post to fence E-W-S.

4-19-1979 at N¼ Cal (1979 Remon Book Page 31)
Took additional RP's: Set a ½" x 25" rod South 84.08 (5½' East of a blazed 9" Burr Oak) on line to a ½" x 26" rod 128.75 South of the corner (4½' West of a blazed 8" Elm)

April 1, 1855 Field Bk. Pg. 53 No. 77 shows ¼ Post
Cor. Sec. 6 T. 1 S. R. 1 E. N.E. ¼ Sec. 1 107-14

843604 (3)

1/4 Cor S 1/4 36 Ovonoco - 108-14

* N 1/4 1 Cascade - 107-14

6-14-93 Set 1" SI pipe w/cap as corner. The corner falls 3' south of ℄ CR #14