/ 10-3-85 CTF/pc

#850406 (1)

¼ Corner 4-5 New Haven 108-15

11-1937 AC Leonard Page 471 Middlepage. J Rock, atty.
a stone was set here by Mr Page Pine Island surveyor
as avered by Mr Clatham Jewell, adjacent landowner.
and about 20 years ago also 5 years later a
stone set at ⅛ corner south which Mr Jewell
helped set. at both fences running west were built
from these stones now apparently gone.
- used corner posts as corners in both cases.

- over.

- meas south 1329.5 to 1/16 fence meet.
- meas north 1106.9 to iron rod then 1618.6 to NE cor 5
- meas west 1686.8 to iron rod then 943.4 to center section 5 - also iron rod 656.4 east of Center 5 for line S.
- on line north from iron rod at 943.4 east of center 5 drove iron rod at 1106.9 then 1653.8 to iron rod on twsp range line.

1966 J Kerr found iron rod on twsp line 943.4 east of N 1/4 5 which was not found. but relocated.

#850406 (2)

¼ Corner 4-5 New Haven 108-15

Gov. Notes- Cushing, Dep. Sur.- 6-12-1854
North on true line between section 4 and 5.
40.00 Set quarter section post.
Br. oak 5 in. S17W 7 lks.

9-20-85, ¼ Cor 4-5: Dug from steel fence post (drive flush) traverse point 6' North, 2' West, and 2½ East. Steel fence post ½' West of the N-S fence Hole 2½' deep on the West side of fence and 1½' deep on east side. Found square post mark centered 4.1 north of the steel post. Line and prorated measure from Center 5th ave Leonard ave came 3.62 North and .83 East of steel fence post so accepted this mark as corner post used

by Leonard. There was also a small post appx 1' West and not deep since 1952 can tied by it. Line and prorated Court measure here 2.1± N and .4 ± E of steel fe post shot.

10-1-85 Leonard Prop. Cor 1106.9 North of 1/4 Cor 4-5 : dug a little by fence corner and dipped for iron but found only an old post stub which we shot. After finding Leonard prop cor. 1679.8 West dug east of post stub and found nut tote found iron in cultivated field appx 1.2 N & 8.15 E of post stub shot. Set spike in nut tote (down 12'+)

10-1-85 : Leonard Prop. Cor 1106.9 North and 1679.8 West of 1/4 Cor 4-5 : Fd 5/8" x 4' re-rod by stub of post. Iron slightly bent. Straightened and put back in hole and shot.

1/4 Cor. 4-5, New Haven #850406 (3)

10-3-85, 1/4 Cor 4-5: Accepted post mark found as corner location (used by Leonard - verified by line and measure west and north) Drove long tekpan with CIC at post location. Came 4.0 North of traverse point and .8 West of the N-S fence. Drove sign and post .75 East.