1 9-21-76 Set C.I.M. #850407 #1
11-25-81 Reset C.I.M. (Different location)
section corner North 4-5 New Haven 108-15.
5-1889 Chas Fraser P 428 no 416 S5 Mr Jewell.
found stake and fence running to it from south
covered set when orig govt stake stood.
- meas west to 1/4 corner in Gordhue Co 10.25 676.5 Chains
that corner coming in center small wash.
- meas west to N 1/4 S 39.59 (2612.94

11-1937 A C Leonard P 473 top page poor survey -
Could find no evidence of corner only recorded fence south.
- run line from N 1/4 S4 to N 1/4 S5 and set stake
39.59 (Fraser record) 2612.9 east of N 1/4 S5. This came
2612.94
- over -

exactly in line with old fence south as recorded.

1966 J Karr B 94 P 47

Meas east from rod set by Leonard at 943.4 east of then N 1/4 S - found meas of 1666' to fence south or 2609.4 R 2612.9 - finally set N 1/4 S at 2610 ± west of this fence south and 922.88 east of SW cor S 32 109-15 - set no corner but 16D at NE S no line.

- Meas east to CIM set in place stone found at N 1/4 4 2636'.

- road fill at NE 5 very deep. corner could only be set by fence south and line of range line.

(#2)

Section Corner North 4-5 New Haven 108-15

#850407

9-16-76 Dug out N½ of E-W road from 24' to 34' W of traverse nail 5' deep to clay. Found nothing. Dug E-W on T.F. measure from stake found at N¼ 5 and also Gov't measure from iron found in bridge at S¼ 32

9-21-76 Set C.I.M. over ½" x 2' rod as corner on line from iron found at S¼ 32 to CIM at N¼ 4 and at Gov't measure from S¼ 32

Corner came 1.09 S and .98 E of traverse point shot in diggings. Corner lies 2' N of ℄ E-W road and 25' W of field fence S

R.P.'s CSO S side telephone pole NE 49.29

Punch hole top W. end C.M.P. to field drive S. S. 27.43

11-25-1981 removed C.I.M. and Iron beneath set in 1975 and reset C.I.M. over ½" x 25" reroad. .33' north to be on line from the So. ¼ Cor. 32 to Sec. Cor. 32-33 as set this survey and at Gov't Meas. from So. ¼ 32. The Corner is 3½' west of center of field drive South and 1½' North of ℄ E-W road.

R.P.'s

C.S.D. in E side P.P. #35 N.N.E. 31.59

C.S.D. in S side C.P. to fence North W.N.W. 118.38

Could not tie to Culvert as in 1975 since field drive was widened.

9/11/85 Jd CIM OK

SECTION CORNER NORTH 4-5 NEW HAVEN (3)

9/18/91 TIE OUT CRN FOR ROAD CONSTRUCTION

TO PT 'L' & RT PI EAST OF OLD BRIDGE TO LINE

BETWEEN N 4,5 & S 1/4 32 359° 59' 42" TO N 4,5

TO S 1/4 32 354.405, TO PI 1674.795, TO V,F PROP. 1031.05,

COR FOR SCHOOL 895.44 NOTE: S 1/4 32, N 4,5, V.F.

COR ARE ALL ON SAME LINE.

PT 'L' 1/2" IRON IN SW COR. OF L SHAPED INTERSECTION

℄ 3rd AVE S.E. RUNNING NORTH E 16 1/2'

LSD IN P.P. NORTH 37.05

SE COR Block fnd. NW 54.93

#850407