9-2-1965 C/M set by Co Hwy Dept., found org stone.

#850505 (1)

section corner 5-6-7-8 New Haven 108-15

9-1882 Hunter P379 No 370 S6 W Drish & others.

did not find corner or attempt To reset it but corner

claimed one stood center road and in line fence W.

5-1900 Robt Fraser P672 No 597 S6 J Deveny & others.

Field OK 15 P53-56

Corner gone, dug extensively for stake claimed set by

Hamilton, found Nothing.

- Meas line S1/4 5 to S1/4 6 short 13 chs ~~set midway~~ Set Gov't Meas.

- Run line from S1/4 6 over 1/16 stake east set by Hamilton

this placed Nothing in line fence west - set 2 stones as corner.

- over -

#850505

10 8-75- (2)

Card #2 section corner 5-6-7-8 New Haven

B293. Meas north to P.O.T & road running S°W'ly.

132.86

Blue 1939 Sta. 7-8-17-18. 79+01.9 Δ 0°16' rt from S.

Sta. 5-6-7-8 131+61.1 to P.O.T.

Meas between true corners both found in 1939 — 5259.2

1941 C.H.D Book # 134 Page 11 - Stone Monument

Gov. Notes- John Cushing- Dep. Sur. Aug. 10, 1854
80.00 Set Cor. of sect 5-6-7-8 Erected mound with trench and pitts and drove charred stake.

7-16-85, Sec Cor. 5-6-7-8: Drove 5/8" re-rod 2.0 South of fence running East (steel fe posts)
π @ 5/8" re-rod. Meas to 5-6-7-8 = 58.99

* Pt C.S.D. (up 6') in E'ly of Twin Burr Oak (by South ~~road~~ yard fence – 3rd from road) to Sec. Cor. 5-6-7-8 = 104° 51' 35"

Add. RP's: Old, Old Disc in South side (up 8") 24" Burr Oak SE 65.96

Spike and CSD in So side 16" Burr Oak NE 65.36

Note: Corner does line with fence running West (across C.R. 5) as described by Robert Frazer in 1980.

This corner will be destroyed by road construction.