#850507

7-14-1965 set CIM over RR spike
9-10-1976 — fd CIM — 6" deep in E Road — Took R.P.'s

Section corner north 5-6 New Haven 108-15
9-1882 Hunter Field Bk 5 P. 144 P 379 No 370 S 6. 2+ Drish & others.
Corner gone also. correction line west as 1/4 on S line S 31
used fence north from S 1/4 31 and meas east 10.96 chs.
also found stake used in sub-dividing S 31 north. By this
line and meas set NE cor 6.
- meas south 43.00. west 40.00.

5-1889. 2 hos Fraser P. 428 No 416 S 5. Jewell.
Field Bk 6 P. 4-8 found stake set by Hunter P 379 and stone by its side.
tested by running a line north as run by Mr. Hart
Goodhue Co surveyor. on a proven section line or 1/4 line.
accepted corner as correct as found.

- over -

-16 east set stake at 19.79½ N&L.
-16 south " " " 22.95½ then 19.95⅚ to ¼ cor
- west. 10.96 (723.36' to 2 9/4 31 109-15.

6-1901 H Fraser P 6 B L 6. H Ickerling & others.
found iron stake driven as corner.
- south found iron stake at 9.31 (614.46 set stone by side.
then 19.21 (1268.86 to old stake (set stone by its side)
- west found iron stake at 5.00 (330'

6-1929 J Kerr P 424 B. L 6 H Zweifel.
found iron stake set pipe over it with boulder under lilac
backed 18.9' as witness.

4-1965 J Kerr found iron, set C/M { 98.05' disc in PP. - ESE / 151.8 - WSW disc in PP
- ~~small rock by boulder under lilac N 18.7~~ gone
- SE cor porch addition & house E & N slope 88.0 west to stone at ¼ cor 2623.6.

Disc PP WSW 151.9
" " ESE 98.03
west to ⅛ bridge bolt 1310.45.