7-14-1965 set CIM in place of orig stone. (1)
#850608

1/4 Corner North 1/4 6 New Haven 108-15
9-1882 Hunter P 379 No 370 S 6. H Druck and others.
Field BK 5 P 144
No corner ever set here, set short stake on sec
line 40 chs west of NE cor 6
- Meas west 40.06 to Twp cor

---

6-1901 H Fraser P 68 S 6. Heckerling & others.
found old stake drove new stake and set stone.
-16 west drove stake set stone on range line at
19.91½ (1314.4' then 19.97½. 1318.35 to Twp cor.
Totals 37.87 chs

---

6-1929 J Kerr P 424 B. S 6 H Zweifel.
found corner set by Fraser P 68

- over -

- Meas east 2626.
- Meas west 2633.3.

Kerr BK 1 P. 40-41 1931
Chained E. from Twp Cor. 2633' and found N 1/4 6 Stone & stake - set new stake & set Plum Tree Due South 1 rod.
Meas. East To N.E. 6 2626' To Iron pipe - found

7-1965 J Kerr.

found 3 X 6 X 10 stone in fence line; with stake east side and below stone.

- Meas east 1313.15 To bridge bolt as 1/16 corner then 1310.45 To Sec corner as set. R Hunter 20.00 John 2626'

16/W Meas west 1312.6 To stone and stake found.

- 1/2" x 4' rod as 1/16 cor - 40 D in Stub NE side 18" bl oak SE 14.8 1/16 corner lies in S E corner edge of old road. as road from east turns south. R east 1314.4

- from 1/16 1317.55 To Twp cor R 1318.35'

RP N 1/4 6-1' S of E-W fence - 2 east of post with brace E side. 496' east to 1" x 14" steel in F south

#850608 (2)

1/4 Corner North 1/4 6 New Haven 108-15

3-26-81 (N. 1/4 Cor.) Found CIM with pipe standing on the North side. Removed pipe and set a survey marker sign and post 1.05 North. This corner 2' South of the East-West fence and 2' East of old brace post in E-W fence