X 10-5-71 set C/M over iron & org stone. ①
#851004

1/4 Corner. 10-15 New Haven 10 8-15.

12-1894 2t Fraser P556 No513 S 10, 11, 14, 15
Acker, Campbell, Ackerman, Shanks and others.

Could find nothing at this corner, nor any evidence, knowledge or B trees to relocate corner.

- run section line set boulder stone M&L at 39.25 5/6 (2591.06'
-16 east set iron M&L 19.62 11/12 (1295.53'
-16 south drone stake M&L 19.97 (1318.0'
-16 center NE 1/4 S 15 drone stake and set boulder at true witness line.

-over-

Surveyors "Sandstone" associates assumed corner
- drove iron in intersection as corner for work south E. (never found)

10-4-71. dug with tractor after running line from
10-11-14-15 and finding rusty hole where iron stake
1/16 corner was set by Dr Frazer 12-1894
- found triangular shaped vertical pointed boulder 16" or more
down 2.5' Set 5/8 x 18" rod under stone with C I M over both
Meas E to 1/16 1292.86 then 1294.65 R M & L 1295.3
~~total~~ 2587.51 R. 2591.06
Meas W to 1/4 9-16 set in line notes from east and north.
2591.1 R 2592.04.
Corner. RPS see Card # 2

851004 (2)

Card no 2. 1/4 10-15 New Haven 108-15

R.P.S. to C/M.

43.5 NW to "." mark in N end 24" road culv top Cente

36.5 SW to single punch hole in rim center top S end "

51.2 SE to punch mark in center top metal tele box metal post. E5B 1

38.25 20' N & E to pepsi cap N side PP# 23765

Corner within 4 exact line from SE cor 10 (10-11-14-15 stage coach axle) and 1/16 iron set in orig iron slate hole

(over details of 1/16 east of 1/4 10-15

10-5-71 found hole in clay, rusty and definate.
26' out in cultivated field where original iron stake had been plowed out.
- set 5/8" x 19" iron in stake hole well below plow depth 15" with lime stone by side of iron
only RP. 26' ± 3.5' S & E to top lone corner post.
in small grass island.
corner within .05 ' of direct line at west end or practally zero at iron set.
Meas east to stage and 1294.65
then to C/M. west 1292.86 R 129553 M & L.

#851004 (3)

¼ corner 10-15 New Haven 108-15

Gov. Notes- Cushing, Dep. Sur. 6-12-1854
West on true line between 15 and 22.
39.985 Set quarter section post.
Br. Oak 16 in. S87W 295 lks.
Made trench.
79.97 Section corner

9-16-81 1/16 South: Dug at calc. location useing CIM's at E ¼, N ¼, S ¼, and stone at W ¼. Found ½" pipe (probably Taylor's) within .1 of this location. The point falls on the East side of the road which is cut to clay. Dug West and N & S to cover any corner by Will Fraser. Found nothing. Set pipe back.