#851205 (1)

7-2-1964 set C/M over 1"x11" pipe with orig boulder up 18" north of C/M.

section corner. 11-12-13-14 New Haven 108-15

12-18 94 W Fraser P556 No 513 S10-11-14-15.

found stone set by Packard and Dutton, alker, Campbell. placed when mound and pits were plain. Ackerman.

-16 west set stake M & L. 20.48 (1351.68'

1-1897 W Fraser P604 No 547 S 11 T. Ackerman

found stone P 556.

-16 north drove stake M & L 19.82. (1308.12'

- Meas west. 40.96.

-over-

5-1898 Jr Fraser P 629 No 569 S 12. F. Ackerman
found stone P604
-16 east drone iron stake M&L 19.88 (1312.08'
-16 north found stake set P604 M&L

4-1903 Ch Armstrong P49B S13 Dixon, Hill, Allis and others.
found stone.
-16 south set stake M & L 19.92½ (1315.05'

6-1960 J Kerr B 81 P23 S 12 Howard Taft.
found stone and 1/16 iron east set S 1/4 12 all
1312' - ~~stone and large~~ triangular boulder by cor post.
7-1964 set C I M one 1" x 11" pipe with orig stone
up 18" north of C I M.
- center 14" bur oak WSW 32.6' 1/16 iron found east
1312.57'

#851205 (2)

Sec. cor. 11-12-13-14 New Haven Twp.

Gov. Notes- Cushing, Dept. Sur. 6-12-1854
North between sections 13 and 14.
80.00 Set section corner. Raised mound with trench and charred stake.

12-9-96 - On Notice Of Adjoining Property Owner Mr. Suther, He Said His Neighbor Had Bulldozed Out The Corner. We Visited And Found The CIM 6" Deep. The Stone That Guarded It & The Corner Post Was Gone. The Oak Tree Tie Is Still There W.S.W. 32.6' By J.K. To Center Oak. Set Post & Sign 1' North Of CIM. The Corner Falls In Line Of Old Bulk Head & 1' North Of Elec Fence Line Running East. The Cor Post To The Elec Fence Running East & South Is ESE 9 1/2'.