X

#851305 (1)

section corner 13-14-23-24 New Haven 108-15.
1-1892 Chas Fraser P468 no 450 L24 F.V An Horn
Corner gone could find no evidence or knowledge except
the old fence south was set from orig corner.
- run line from 1/4 13-14 to L W 24 and set iron
rod as corner 1/3 distance 39.78 1/3 (2625.7. and in
line fence south as lines E & W worst in county.
- this brought N-S line in line of fence west also
claimed set from orig corner.
-16 south set stake M & L 19.89 1/6 which came 5' into river
took 12" black ash L 45° E 15 lks as B T.

- over -

4-1903 Ch Armstrong P 49 B S 13 Shay, Van Horn and others
used corner fence post.
-16 north stake M & L 19.92½ (1315.05'
-16 east stake M & L 19.94 (1316' line east rough.

12-1894 H Fraser P 557 No 513 S 10-11-14-15 6 parties
used corner set P 468 To run line west to S ¼ 15 to set
S W cor 14. - 40.24 5/6 (2656.4 each half mile.

6-1947 J Kerr B 34 P. 40 S 14 H M Lehman.
Run line from S W 14 east. set 3/4" square bar at 660' then
axle shaft at 39.76.63' or 3/4 accross S line 14.
- found small L.S. on top of larger L.S more than 1' deep. at SE 14.
- set well point with 1¼ pipe riser on top.
- total mile 5302.5 W Fraser 5312.8'

See card 2 for corner found by McShue & Betts. when done.

Sec. cor. 13-14-23-24 New Haven Twp. (2)
#851305

Gov. Notes- John Cushing, Dept. Sur. Aug. 10, 1854
80.00 chs. Set post to corner of sec. 13-14-23-24
Raised mound with trench as per instruction
drove charred stake .

10-1985, Sec Cr 13-14-23-24: Found 1¼" pipe set by Ken. Pipe on West side of newer corner post (set in concrete) to fence N-S-W. Pipe into West edge of concrete and post being pulled west by fence had bent pipe ½'± west. Bug down on West side of pipe to soft point where pipe still straight and took shot then. Can't replace pipe without removing corner post. Surveyor should not use top of pipe. There is an older post standing 1½'± West of pipe.

10-29-85, Sec. Cor 13-14-23-24: Found 5/8" x 12" sq. headed bolt standing 2.64 N and 1.64 E of Kent corner and 2' E and 1/2' N of old C.P. (and down 6'). Probably T. Fraser's corner.

No cert on this corner. Make decision!!