10-20-81 CIC

#851606

1/4 Corner 16-17 New Haven 10 8-15.
12-1873 Hunter P235 no 237 & 17 McDonald & others.
found orig corner standing in mound. tested & E B T
which was blown over, found it 142 lks rather than 133 L.
also stump of S W B T. also slight difference by Mr
Kanes aner left stake as is. (Iron corner 4 farms.

No mear of any kind

Gov. Notes + Cushing, Dept. Sur. 6-12-1854
North between sections 16 and 17.
40.00 Set quarter section post.
Aspen 6 in. S22E 133 lks.
Aspen 10 in. S5W 167 lks.
41.50 Abrook course S. E.

10-20-81 ¼ Cor 16-17: Set a CIC/p² as the corner on the SE side of a large Elm tree stump used as the c.o.p. to fences N-S-E-W. Put survey marker sign on wood post driven on the East side of the monument.
RP's: C50 in top of brace post S5W 25.50