6-3-80 CIM #851804 ①

¼ corner 18-19 New Haven 108-15

3-1892 Thos Fraser P471 No452 S18 P Kennedy, D Kane.

Set drag tooth as corner on line & gov't pos meas.

- Meas east 40.05 2/3 2643.73 Govt 40.00.
- Meas west 38.85 2/3 2564.53. Govt 38.80.
- 16 west plat shows 18.82 5/6 and 20.02 5/6 no dec. 1342.67. 1321.87.
- 16 east set stake N & L 20.02 5/6 1321.87 to iron stake set. 12" D. oak S 44½ E 47½ links.

Btree ¼ 18-19 taken 3-1892 N 51°50'E 42½ lks 28.05 8" D. oak

10-29-71. Co surv. dug entire south half of road on line fence north which came at 2650.5 from 00 nail

(over

at 17-18-19-20 which was. 7.45 E of iron shaft found
on 2642.5'. R Hunter 1856 2644.0 T Frazer 1892 2643.74
-1/16 fence east came at 1317.4 from iron shaft at 17-18-19-20
- set nothing or referenced nothing at corner.

6-12-1854 Gov't Notes- Cushing, Dept. Sur.
East on true line ~~between~~ between 18 and 19.
38.80 Set quarter section post.
Jack Oak 5 in. N45E 30 lks.
Jack 4 in. S15E 58 lks.
78.80 Section corner.

Sept, 1856 Thos. Hunter Pg. 16 No. 26 Shows 1/4 Post.
1/16 East 20.03 chs. M&L - B.T.'s (S50½°W 1½ lks. X S61½°E 9 lks.)

6-2-1980 (1980 Remon BLC P. 5-1) 1/4 Cor 18-19 Dug hole 3' N-S
by 6' E-W just to be sure that we dug far enough
South in 10-1971. Found that we did dig far enough
South to cover E-W line location as per T. From 1892 (15.07N
9.37E

1/4 Cor 18-19 New Haven 108-15 (2)
#851804

6-2-1980 (1980 Remon. BK. Page 51) 1/16 East: Dug hole 4' N-S x 6' E-W at 1/16 East. 10' South and 4' West of Trav. nail was center location of this hole. Old road bed 2½ deep and clay under it so no corner could be found.

6-2-1980 (1980 Remon. BK, Page 51) 1/16 West: Dug hole 4' N-S x 6' E-W at a point 5.5 No. & 1.5 East of traverse nail at 1/16 cor west of 1/4 Cor 18-19 Old road bed about 2½' deep and clean yellow soil under this road. Did not find anything.

6-2-1980 (1980 Remon. BK, Page 53) 1/4 Cor 18-19 Set a CIM over a ½" x 18" rod on line between the section corner and at prorated Govt measure as per

Thomas Fraser's Survey No. 452. Corner 1½' West of fence line North and 7½ South center of E-W road.

RP's CSD North side pole (no number) SE 61.00

CSD East side corner post NNE 42.49

Spike & CSD South side 24" Burr Oak (up 5') NW 113.87

E

File with WAB-19 New Hagen

Dodge County Corners T108N R16W (3)
#851804

5-23-1980

1/4 Cor 13-14 (1980 Remon BK) Measured from the line of fences E and W at the 1/16th North of Sec. Cor. 13-14-23-24 South 1327 (rough) to 3/8" rod found in center of intersection (H.A. Crampton set this 1/16 midway 20.04 in 1897)! Measured from the same fence North 13 22½ (rough) and dipped a bolt with 1¼ sq head down ½'. This bolt in driveway of farm and in line with the West edge of road South and North edge of road farther East.

Took approx RP's

18" Butternut tree SW 25'

Power Pole (with transformer) NE 34

SE Corner Garage NNE 18.3

5-22-1980 1/4 Cor 13-24: Dug with backhoe from traverse nail set in line with fence South and 4' South of ℄ E-W road North 10', South 3½', East 4', and West 4' by 3' to 4' deep

to clay. Found nothing. Measured 666½ East to 1/64 fence N.

5-23-1980 ¼ Cor 13-24: Dug again with backhoe on line from East 13-24 to a point 4' to 5' North of the 3/8" rod at Sec. Cor 13-14-23-24 (at Crampton's measure from 1/16 fence North-See Old Book A, Page 267 Dodge Co.) and at Crampton's measure from E 13-24. Hole from traverse nail North 5', South 1', and West 7'. Found nothing. We had dug about half of this already.

5-23-1980 1/16 East of ¼ Cor 13-24: Dug with backhoe in center of road and at Crampton's measure from E 13-24 which came 4' East of fence North. Found 1" shaft with gear 2½' deep 4.6 North and 4.4 East of the traverse nail. Left as found. Corner is 4 & 4' East of fence North.

5-23-1980 ¼ Cor 13-24; Dug hole again centered over a point at double the line and measure from E 13-24 over the iron found at 1/16 West This point came 10.32 N & 2.03 W of the traverse nail. Found nothing Dug from a point 9' North of the t.n. North for 5' and West for 6'