1 10-15-71 found pipe - set 5/8"x30" rod #852104
11-7-72 set C/M. over pipe below.

1/4 corner 21-28 New Haven 108-15. (1)

5-1863 Compton P70 no 99. S28 Blanchard & others.
stone with cinders on plat. used to set center 28.

---

10-1969 Perk Higham D County surveyor set iron rod flush road surface for SE corner Badmgardner land. on ply line from SW cor 21 up center road running east. Did not dig or did not have either S1/4 21 or SE cor 21 - rod at S1/4 21 Near center or slightly north center road in line fences N & So.
12-4-69 I Keir. found 21-22-27-28. or SE 21. On line established by Higham projected east on 40' ③ N it missed corner found 37.3' or 2.7' so rod at 21-28 to be on line would go 1.35 north. this does not mean above stone if found will be on this line - no E-W fence Corner.

10-15-71 Co surv. dug carefully with Charlie, did not find any traces of any stone, cinder or glass. road signs deep. - found 1½" pipe 3 feet deep .25 south and 1.47 east of Hyham rod. pipe found now 1.6' south of direct line between sections corner - set ⅝" x 30" rod

28.11' south to head of cone nail E side 10" oak cor post.

137.35' WSW to pipe cap N side power pole # 23033 corner slightly east of fence south near center road.

origin of this corner unknown. Armstrong worked in area years past.

7-7-72. found iron set as reset 10-15-71 set C/M. 3" below surface. (pipe still below).

~~Humboldt~~ 1/4 corner 21-28
Cast Iron Witness Corner 1854
40.00 Set Iron 1/4 steel post
West on true line between said sections 21 & 28
39.99 Set 1/4 steel post from which
Aspen 6" in 15 W 36 W 20 L
Bur. Oak 10" in 15 S 81 E 17 L
5-15-79 Shot CIM for C.H.O.

#852104 | 2