R.R. Spk by K. Ewers (Tom Ferguson) Set wrong
#852409

1/4 Corner Center 24 New Haven 108-15

4-1871 Perry by Hunter P181 No 192 S24 N McCullough
set stake inters line from all 1/4 corners.
- meas east 39.52. (2608.32
- south. 19.62 M & L then 9.81 M & L To S 1/4 cor.
1294.92

4-1892 J. Fraser. P468 No 450 S24. Frank Van Horn.
did not set true corner as Transit broken by accident.
after completing E-W 1/4 line. set stake on said line 39.52 chs
2608.32. ~~east~~ west of E 1/4 24.
- north set stake Midway no meas no line.

10-1985, Center 24°. Found Keith Ewers RR spike under B.T. overlay on C.R. 12 2.03 N and 10.36 W of t.n. (in ℄ and in line fence N. and 2½' E of C.P. in So side of road.

10-29-85, Center 24°. Dug from t.n. (set in ℄ E-W road and in line fe. N&S for 1'+ N, 1'± S, 1' E, and 2' West to check this location for Hunter's stake and check condition for larger tractor dig. There was a road down 1½', then 1½' to clay but very mixed to clay. Fd nothing and condition poor for larger dig.