#852605

X 10-22-68 set 1" x 5' pipe with org stones arround pipe

section corner 26-27-34-35 New Haven 108-15

2-1882 Hunter P 373 no 364 S 35 C Gates, J Bryant found corner standing, tested by all identified witness trees or stumps proving corner correct.

-16 south found stake standing N 0 L 19.88½. (1312.4'

-16 center NW ¼ 35 set marked stake N 0 L 20.15

1329.9 on E-W ¼6 line 6" S oak S 35° W 44 lks (29.04'

also 6" S Oak N 40° W 14 lks (9.24'

1-1902. 2r Fraser P 28B NW ¼ S 35 E.W Saley.

found stake standing, evidently left as is.

-south set temp stake 3.37½ (223.08'

-16 south found stake set in former survey -over

set stakes 7.25 (478.5 east of 2 above corners

6-1946 J Kerr B 30 P 57 & 34.
found limestone at fence corner covered as true corner.
- south found or set stone at fence corner south 327.63
- 16 south found remains of stake P 373 driven to bedrock south of corner fence post - reset with 2" stake and 6x8x10 boulder by side 10" elm. NNE 5.7'

10-22-68 J Kerr set 1"x5' pipe up 10" in place of lime stone in springy wet hillside - orig stones by sides of pipe.
- south found stone 327.6 on east side new cross corner post.
- 16 south did not have proper equipment to find corner elm now over 18" dia - corner fence N & W 6' west & 1' south of tree indicating stone in clear open grass land south.

New Hanna Section corner 26-27-34-35 #852605 | 2
Cor. W. Ties Cashing 1854
60.00 Std post for corner to Sec 26-27-34-35
Aspen 6" N 52° E 34 L
Aspen 12" N 52° W 88 L
Aspen 10" N 86° W 60 L

Jan, 1862 Samuel McDowell Pg. 67 N/a 94 Used Sec. Cor
For breakdown of West 1/2 sec. 35

8-27-93 Fd John Kerr pipe in good condition.