X 10-15-71 found stake & stone
9-7-72. set C/M over stone and cor.

2 Cards #852804 (1)

1/4 Corner 28-33 New Haven 108-15.

12-1897. Jr Fraser P 6 14 no 558 L 33 J. Ottman, A Hurd had located corner (old stake) at L 1/4 33 in 8-1893. D Pierce. no mentioned what section used in N 1/4 33 gone.
located corner M & L 39.80 - set stake with stone
fg To side. (1/4 28-33 as "B" (2626.8
S 16 east drive drag torch M & L 19.90 (1313.4'
-16 south set stake M & L 19.88. (1312.08 with stake
south M & L 9.94 (656.04' to center 33 stake found

9-1910 Ch Larson P 130 B SW 1/4 28 Lake, ward, Pierce
found corner set previous survey.

-over-

- Meas north 39.95 (2636.7 to center 28 o marked corner post. set unrecorded point likely midway.
- west meas 39.82. (2628.12 set stake at 821.37' then 624' then 1182.7 to SW cor 28 & to corner set by line & meas from SW 33 and 1/4 32-33.

10-1946 Co Hwy Dept B 149.149. - 5-20-46
found 12" boulder and limestone with 3/4" rod riser set by Sp Hub S 75.0 Sp Hub N 75.0 on [redacted] Transit line
Meas NW cor 33 to N 1/4 33 2626.6 - also cont thru east equal meas and set hub as NE corner 33 (dup words.) Rough.

12-2-70 Co surv - found axle shaft at 28-29-32-33 meas east carefully 35° temp lined center bottom large leaning corner post & main brushy fence north (light brush) at 2625.5 nail line 36.2 N to open hole 2300' R Fraser 2626.8 Co H D 2626.6 - cont east no chance of drag touch recorded P614 being in place deep cut in curve - will transact

Card #2 1/4 28-33 New Haven. #852804 (2)

W Fraser found Center of section 33 to be 10.1ks or 6.6' Too far east on line from true S 1/4 33 over true center to the 1/4 28-33 stone set M & L 2626.8 indicating original govt corner used to set Center 33. P18 no 30 by Hunter. May be considerable east of M & L at 1/4 28-33

10-15-71 dug with tractor, found 6 x 8 x 16. boulder stone with recorded stake on south side. drove 1/2" x 34" reinf rod in stake hole at corner, set small rod riser.
- meas west. about 2626.1 R 2626.8
36.15 just E of N. 14 to pepsi cap in PP # 23001.
39.7 5' E & S to hard rail in knot W side tile pole.
- meas east to final corner set at 27-28-33-34 on risers
Meas.

1/4 Corner 28-33 supposed set M & L by Dr Fraser
2626.8 now 2626.1 west and east 2629.1 ± (traverse)
but corner not on direct line as now set.
1/4 corner about 1/2 & 3.9' too far south to be on direct line.

7-7-72 found iron set C/M. above iron set below
10-15-1971. set no further RPs.
Corner near center road in line very poor fence north.
Cor/ W-to Cor-ing 15.5 ±
40.00 set temp 1/2 set post
West on true line - bearings set 28 & 33 N 89°12' E
39.90 1/2 set 1/4 set post in which a
bur oak 16" 539 W & L
White oak 6" W & E 9 L

May, 1863 P.C. Compton Pg. 70 No. 99 shows 1/4 Post used to set Center 28 at intersecting lines.