#852805

11-10-71 found and pinned iron as corner. 2 Cords (1)

section corner 28-29-32-33 New Haven 10 8-15-

7-7-72 set C/N over iron 3/4" x 26"

4-1875 Hunter P 269 no 267 S 32. S. Malcom & others found stone in center road. covered as having been set where orig stake stood by C & Frost and others.

-16 west set stake M & L. 19.98 1/4 (1318.8'

-16 center NW 1/4 32 set stake M & L on N-S 1/16 line 19.99 (1319.34' 8" Jack Oak N 22° E 11 1/2 links.

1-1895 H Fraser P 590 no 536 S 29 H Frost & Bro. found stone P 269.

-16 north. set stake M & L. 19.95 (1316.7'

-one

-16 west. set stake M & L. 19.97 1/2 (1318.35
with 1/64 stake west 9.98 3/4 (659.17

12-1897 W Fraser P 614 No 558 L 33 Ottman Hurd Purie
found stone P 269. -Meas east 39.80 to M & L.
(2626.8!

6-1910 Ch Larson P 130 B L 28 Luke Ward Purie
set corner on direct line from L W 33 over W 1/4 33.
39.90 north no other meas given south.
39.82 east to L 1/4 28.

Co Hwy Dept has 3/4" iron rod down 8" 10-1962 B 149
- cross in school steps L W 102.3. P 49
- spring leaf in fence line L E 78.0 Meas east 2626.6

6-28-1910 Ch Larson P 128 B. L 32. H Luke
set stone 6 x 12 x 21 hole understone filled with lime.
Meas west 19.95 M & L.

#852805

Card #2. 28-29-32-33 (2)

New Haven 108-15

1940 DCO B103 P59. found 2" auger hole full of lime
set 1" axle in hole.
V knotch in N.E. cor. of 1st step in school entry S.W. 102.3
steel spring leaf in fence line S.E. 71.0

1946 CHD B149. P.49 found 3/4" steel rod center inters 8" dep.
cross in school house steps S.E. ? 102.3
spring leaf on fence line S.W.? 78.0?

12-2-1970 Co surv - used R P from school steps S.W. the
indefinate due to chipping & very old concrete, school a wreck.
Got very faint dip lining R P and center E-W roads
found end of large axle shaft down 18" on center E-W roads
within 23' of line fence N on E side road - 8' E of road south (over)

set hub one corner - meas east 2625.5 to line fence north - center bottom leaning wood corner post & brush on fe N.
and 36.2 N to pepsi cap PP 23001
RPs - extreme NE corner bottom slip of orchard SW 101.5
20 D nail in pepsi cap NE side 14" cor fe post SE 42.7
- point of angle corner post NE 40.72
" " " " NW 50.8
pepsi cap on S.W. side PP# 22990 NW 57.4

11-10-71 dug with tractor from 2' east of iron to 6' west. 3 to 4' wide. found lime hole below road as county records, plain and deep. - road levels deep, near 5'
- set 3/4" x 26" reinf rod as temp corner!
final RPs to center lime hole with rod viper.
40.65 NE to edge angle corner post edge ↑ halfway up.
42.83 SE to pepsi cap on corner post large oak post.
57.3 NW to pepsi cap on SW side big power pole # 22990.
39.1 SW to ⁂ on West top center 18" galv road culv.

New Haven section corner 28-29-32-33 (3
Cast Stone corking 1854 #852805
80.00 S-W post to corner for sec 28-29-32-33
Bur Oak 8 in S 11 E 12 L
Aspen 6 in S 11 W 48 L
Aspen 4 in N 40 W 60 L

May, 1863 P.C. Compton Rg. 70 No. 99 shows Sec. Cor.
(See survey for Interior breakdown of Sec. 28

7-23-99
EA MC

852805" SEC COR 28-29-32-33 108-15
FOUND VF 5/8" PIPE W/PLASTIC CAP DOWN 0.9
IN GOOD CONDITION. CORNER FALLS 1/2' N
OF ℄ 85TH ST NW + 4 1/2' E ℄ CR 105.