3-4-93 VF SET 1" PIPE /CAP

#852906

1/4 Corner. 29-30 New Haven 108-15

11-1874 Hunter P264 No 262. S 30 (E½) R Comfort and others

quote " 1/4 post missing, but both witness trees standing.

found remains of old stake. at point indicated by

field notes. set new 1/4 post in its place properly

marked. -16 west set stone 3 X 16 X 24. M&L 19.92.

- 1314.72 - also set stake 6.30 chs (415.8 east of Center 30.

5-1877 Hunter P306 No 301. S 20-29 H.W. Lamberton.

found stake set P.264

-16 E. set marked stake M&L. 20 12½. (1328.25.

to center section 29 (stake set intersection. (over

10-20-71 corner hopelessly lost. deep gully in area. fouled up by road carving in westerly directions
- found limestones at Center 30 and 1/16 east of center 30 both exactly as recorded P. 264 so corner could be replaced exactly. line very rugged. especially west 2/3 of 1/2 mile. Clear spot possible north 200' on west half while opposite on E 1/2. should stay on or near line & brush & cut way thru.

Gov't notes:
40.00 ch. set 1/4 Sec. post
B.Ts 18" Elm S75°E 11 lks.
16" Lind. N75°W 19 lks