¼ Corner W¼ 31 New Haven 108-15

8/7/89 C.H.D SET 5/8" BRASS PLUG #853106 (1)

Nov., 1978 Dodge Co. Surveyor, Ron Murphy, reports finding a 1912 C. Larson survey in Sections 25 and 36 108-16 in which Larson mentions this corner but does not say what was here.

5-8-80

W¼ Cr 31 (1980 Lemon BK, Page 26) Dug with backhoe from traverse nail East 1½' to ℄, West 8', North 3', & South 9' by 2½ to 3' deep to clay. Condition poor. Found nothing. Dug to cover line from SW 31 to NW 31 at C. Larson marker from fence at 11.9' W and midway, and also ℄ road West LRP } CN E 13.36 CN N 10.42

5-12-80

W¼ Cr 31 (1980 Lemon BK, Page 29) Dug from ℄ N-S road East for 7' and opposite hole dug 5-8-1980. Very poor condition. Found nothing. We were digging E-W to cover the ℄

of the old road as determined from Dodge Co. Records and N-S to cover the ℄ of road West and also midway (℄ old road 3-4' East of present ℄)

1/16 South (1980 Remon. BK.) Dug from 1' North ℄ road East South 7' and from ℄ N-S road West 7' to 2½ to 3' deep to clay. ~~Found nothing~~. We were digging to cover line from SW 31 to NW 31 and also from SW 31 to ℄ of old road at W1/4 Cor 31 as determined from Dodge Co. records and N-S to cover midway from SW 31 to the ℄ of the road West at the West 1/4 31. Found only a 1" x 2" hub in ℄ N-S road and in ℄ road East
5-12-80
Note: We previously chained 1320 (rough) from SW 31 to a point 1' North of the ℄ of the road East line.

5-19-1980 (1980 Remon. BK) W 1/4 Cor 31: Set a ½" x 18" as the corner 3½' West of ℄ N-S road, 1' North ℄ road West and 14' South of fence East. Corner set on line SW 31 to

1/4 Corner W. 1/4 Cr 31 New Haven 108-15 (2)
#853106

5-19-1980 Continued: NW 31 and N-S such that the 1/16 North is held near fence line East and 1/16 South is held near 33' North of row of huge Maples running West on South side of road West.

RP's: CSD in SE side pp# 23176 SW 47.72
Punch hole in top Nutt end 18" C.M.P. in road West NW 35.41

5-19-1980 (1980 Remon. BK) 1/16 North: Set a 1/2" x 18" iron midway and on line. Corner 2' West ℄ and 1' South fence line East

5-19-1980 (1980 Remon BK) 1/16 South: Set a 1/2" x 18" rod midway and on line. Corner 2' South ℄ road ~~East~~ West

and 5' West & N-S road. Corner came 33'± North of line of large Maples running West on South side of road West.

RP's: CSD in pp# 23101 SW 43.75
CSD in pp# 23171 NW 48.89
CSD in pp# 53100 SE 59.01

Bearing Trees,
10.00 Inch quaking aspen pole.
B.T. Oak 6" N 85° E 2¼S
B.T. Oak 5" N 5° W 3¼S

7-15-85, W1/4 Cor 31: Corner may be destroyed in road construction. Took additional reference. Set 5/8" re-bar at N. edge crushed rock road running West, at ℄ of field drive on North side of road. Pt. lies in fenced running East @ W1/4 31. RP to Rd ℄ C.S.D. in pp# 23177 (SE side) SW 49.85
T @ Red mees. to W1/4 31 = 308.24 x Rt V W1/4 31 to W1/4 pole of pair of poles in N-S transmission line 1/4± mile E = 290°27'09"

1/4 CORNER W 1/4 31 NEW HAVEN 108-15 (3)
E 1/4 36 DODGE CO.

8/7/89 C.H.D. SET 5/8" BRASS PLUG IN ℄ C.R. #853106
#5 RP.
CHD DISC. IN P.P. SW 63.38'

1/16 S OF W 1/4 31 8/7/89 CHD SET 5/8" BRASS PLUG IN ℄℄ C.R. #5 & C.R. #14
RP's
CHD DISC. IN P.P. SW 69.82'
CHD DISC. IN CUT OFF TEL. POLE NW 82.55'
CHD DISC. IN CUT OFF TEL. POLE NE 84.60'