X 4-9-71 found limestone. #853204 (1)

1/4 Corner south 1/4 32 New Haven 108-15
north 1/4 5 Kalmar 107-15

4-1875 Hunter P269 No 267 L 32 L Malleau & others.
found org stake standing, tested stumps & B trees
-16 east set stake M&L 19.89½. (1313.67
-16 north drove short stake M&L 19.86½ (1312.09 flush with road surface. Bearing line E-N89¼E N-S1°E

6-1910 Chas Larson. P128B L 32 H Luke.
found stone stated as set by former survey.
-16 east undescribed corner M&L 19.91. (1314.06

Co Hwy Dept 1935 Book 78. P 95
found square limestone at fence corner.

over.

4-9-1971 Co surv. ran & meas line from S 32-33 C I M. west.
Offset 2.28' N at corner. set nail at 1313.0 R Hunter 1313.07. Larsen 1314.06.
land gently rolling, to 1313 then very steep slopes and ledges. and trees.
Offset 10' South which made line opposite stone found at 1308.76.
9.1' south of stone. left nails at 1157.63 and 993.4
stone 4" x 6" top under new fence north just 4.0' north of new
corner post. Its understandable that west ½ would fall short.
due to severe slopes. left R.
nail at 1/16 corner 2' north and 1' west of corner post as it leaves
ground. Tilted some east due to fence tension. If owned go
11.59 south and 2.12' east to be M & L.
total ½ mile 2621.76 1310.88 midway.
– 4-14-71 meas from west stone at S 1/4 31, 5313.2
so reset S 31-32 midway at 2656.6 but not on
line – S 31-32 owned figure 5.5' S of direct line
between 1/4 corners (set S 31-32 on direct line from west.

1/4 Corner South 1/4 32 Newhaven 105-15 (2)
North 1/4 5 Kalamo 107-15
Geo Notes #853204
10.00 Det quarter section corner
Black Oak 12 N 30 E 54
B. Oak 14 S 75° E 17
3/28/90 Vince Fangman Fd limestone 4' north of corner post under N-S fence, Drove a 3" wood post ± 1 foot north. Rp's 7.52' to 30d spike in 4" cherry S.W.
43.87' 30d spike in 12" Oak ESE
34.47 30d spike in 15" elm NE