/ 12-2-70 set fed rail & steel post below in place old stake hole ①

section corner south 33-34 New Haven) 08-15
#853405
north 3-4 Kalmar 107-15

12-1897 Jr Fraser P614 No 558 L33 J. Ottmari
A Hurd, D Pierce.

found stake which a Mr. Basset avers he set in place of orig govt stake, this stake found in survey made in 1893 and replaced at that time with stone 4x18x25

-16 north set stone M & L. 19.90 (1313.4' 2621.5
-found S 1/4 34 stake & B mound stone & stake chg east 32.72
12-1916 JKerr. P264 B. SE 1/4 33 Thos Fraser attorney
run line from S 1/4 33 east to S 1/4 34 5233', set over-
stone. 6x6x30 Midway at 2616.5 R P614 2621.5

took witness tree S 33-34 S87°E 12" maple 25.5'
-16 North stone found 6x6x14 M. Frasers corner.
Line and 1321.5
North then. 1314.5 To 1/4. 33-34 - set stone 651.12 West
of above 1/16 corner then 1953.38 west to to cor N of S1/4 33

Co Hwy Dept used something as corner.
1354.4 north to south edge road 1948 B155 P1
1/16 corner 329' south of road. 1321.5 1/16 not M+L then.
1314.5

1966 J Kerr B94 P61. Cline Brown S3 107-15.
Meas from S1/4 34 west. for east bank river traverse.
2334.7 To point ( ) on east river bank for start of traverse.
J Kerr

1931 Book 6 1931 #2 page 3 same info as P 264 B.
except line rerun from S1/4 34 west to S1/4 33 Meas now.
5224.68. 1916 Meas same line 5233.0 survey says
set corner M & L. 2612.34. no dist to cor. (over

Card # 2. Sec Cor. S 33-34 New Haven 108-15 (2)
N 3-4 Kalmar. 107-15
#853405

1935 CND Complete B78 P7. No desc of corner
found stone and stake at 1/16 cor north
-road alignment then. 14' north of 1/16 stone.
centerline
Meas shown from 1/16 stone south 1321.5 measurement from north 1314.5.
former survey

11-12 to 17-1970 offset 50' east of CIM at 1/4 33-34 and 50E
of iron pipe 330' south cont line south. found 1/16 stone
finally at 1311.9 WF 1313.4 JKen. 1314.5 - stone 38.78 W
of random line. - cont same line south. @ back 50' at sta
9480.14 cont to 2639.52 or 1327.62 from 1/16 stone S.
WF 1313.4 JKen 1321.5. probed extensively for corner
stones at Meas from S 1/4 34 etc 2648.06 to random pail.
(over)

12-1-70 dug for corners extensively - found stone recorded P264B 6x6x30 with cross in top 3.8' deep set 1916. - also found border reel shaft with all reel slat holders intact with at least 15 rocks+ stone about it about 15" deep set 1931 B6 P3. it is evident this was when some 18" above ground. - also found 2 stones about 1' long lying flat about 3' dup in near exact area W Frazers corner. with stake hole running near 18" to 2' below stones - set 1"x4' pipe on 6x6x30 stone, 3/8"x18" on border reel corner. set 4' long steel fence post with bottom evidently broken off in stake hole. will set pipe corner post as temp. or perm corner.

12-2-70 set 5' 2" angle iron rail as corner up 4" fit around 4' steel fence post pile - pulled border reel corner and buried SW of corner up 3" and piece of angle steel fence post on NE side corner pulled pipe post 6x6x30 stone left below.

see card 3.

Card #3 S 33-34 New Haven 108-15 (3)

12-2-70 set 2 RP tube to witness 3 corners found.

	W Fraser cor.	1916 J Ker cor	1931 J Ker cor.
40 D in tube on E side 20" maple NE.	57.45	60.48	58.48
40 D in tube on E side 12" box elder SSE	33.38	23.76	22.95
edge water, W edge river E	68.0		

#853405

W Fraser corner as set comes 1311.95 south of 1/16 stone and 2620.33 from S 1/4 34 R 2621.52 and lines perfectly from 1/4 33-34 as reset 5.3' west of C/M set 1965 ceremoniously. - Near north from 1/16 to C/M 1311.9. will set new corner at same.

1916 J Ker corner came. 1319.19. south of 1/16 stone and 2613.67 west of S 1/4 34 R 2616.5 and 6.65' east of direct line described above.

1931 J Ker corner came. 2610.47 west of S 1/4 34 R 2612.34 and 1318.44 south of 1/16 stone and 9.85 east of direct line one 1/16 north final.

12-2-70. Co surv set headed nail in center black top road on line west side S 34 from ⑤ line and 1/16 corner.
- nail came 33.76' north of cross on 1/16 stone.
RP nail & pepsi cap E side new cor post. E NE 39.25
nail in pepsi cap (plumbing 2') (1/16 RP) corpost S W 32.05
nail " " " " 3' " P Pole. S E 64.8
- set long cast rock weight on E side 1/16 stone, covered up.
angle of ℄ road running east to sec line south to rock 84° 37'
angle of 1/16 line west (1/16 stone to stone W 65.12) and section line between 33-34 west to north. 89° 20'

Nov. 1856 Thos. Hunter Pg. 18 No. 30 Shows Sec. Cor.
1/16 North 19.80 chs M&L - B.T.'s (N 82° W 12 lks.) (S 50° W 59 lks.)

Section corner South 33-34 New Haven 108-15 (4)
North 3-4 Kalamazoo 107-15

#853405

Govt Notes

80.00 Set post corner to sections 3-4-33-34

Willow 10 N 35° E 16
Elm 14 N 49° W 120
Elm 20 S 15° W 95
Ash 10 S 57° E 61

8-15-1893 William Fraser, Deputy Co. Surveyor (pg 18, No. 30) added note to Hunters 1856 survey. Found stake at section corner claimed to be where the old govt corner stood, planted stone 25" x 18" x 4"