10-21-65 JKerr B90 P72 set C/M over 1/2" x 12" rod. 12" deep on line 1/16 chain north and 1" inje 330' south. 1306.5
- This corner wrong as there is proven kink in this line.
11-9-1971 reset C/M in Correct Location 3 cards ①

#853406

1/4 Corner 33-34 New Haven 108-15
12-1897. 21 Fraser P614 No 558 & 33 J Attman
A Hurd and D Pierce.
found remains of old govt stake in ground, tested by NEBT and govt notes & found correct. set stone in its place.
-16 south set stone M & L 19.90 (1313.4
-16 north set drag north M & L 19.82 1308.12
- west set property stakes 4.93 (325.38 for line north, then 4.93 (325.38 for line south then 10.85 (716.1 for line south - stakes from center 33 east for lines north are 493 (325.38 - then 9.85 (650.1 (over

then 4.93 (325.38' all for lines north which overlap.
19.71 (1300.86 from center 33 E
20.71 (1366.86 " 1/4 33-34 W.
N line of NE 1/4 33. 2626.8.
EW 1/16 line " 1306.14 M & L or 2612.28.
E & W sides both straight, comp meas E 1/4 to Center 33. 2597.76

12-1916 D Williams, Surv 8264 B L33 T. Fraser & attorneys.
found stone in place as 1/4 corner.
- meas south to 1/16 slow found. 1314.5
- set stone 6x6x24 1/4 dist to 1/16 on N S 1/4 line west 651.12
- meas south 4 1/16 to 6x6x30 set M & L 2616.5 betw 1/4 corners on direct line between 1321.5.
some time a 1" pipe was set south 330' lately by a Fraser.
Corner stone removed and destroyed by Leonard Thoon in removing brush & trees from area in 1950s or near then (C# 2)

Card # 2 1/4 33-34 New Haven 108-15
#853406 (2)

10-1965 JKerr B90 P72 Sec 33 L. Moon
relocated corner on direct line between 1/16 shaft, agreed to be where drag hook was found and 1" pipe just east of corner post & fence west and 1306.5 ± shaft & 30±
N & pipe set C I M over 5/8" x 12" re bar.
- pipe lies east & cor post & fence west about 85' south of 10" elm at fence in edge cult. field, tree near line north or east some (18"). This corner replaced in error as a considerable angle is evident at 1/4 corner by accumulated notes. E-W lines N to S. 2626.8 - 2612.28 - 2597.76.
E line N 1/2 •, E line S 1/2 2597.76 - 2604.5 - 2612.34.
- figuring split & sum of N & S ties - 2597.76 would show kink of 20.81 from direct straight line. OVER)

11-12 to 17-1970 Meas C/M at 1/4 33-34 south on 50' ⓢ E and 50' ⓢ E at pipe 330' south (329.9' exact) 340. finally found 1/16 stone at 1311.9 and 38.78' west of 50' ⓢ. dug west of C/M to clean clay (16" deep) found stone chip and dark dug area with apparent stake hole on N side .4' south and 5.3' west of C/M also larger dug area. 3.25 north and 5.8' west of C/M - using 5.5' west and 1/16 stone and 1313.0 would bring line .8' west of 1" pipe on cor P. - R P to 1/64 cor west of 1/16 stone 651.12 - 88.0 N to ℄ black top 94.0 ESE to center 42" maple - 76.55 ENE to center # plate 22698 P pole. - R P to W Fraser 1/16 stone 4" x 9" top deep - 33.9 N to ℄ black top. 33.3 SE to pipe cap NE side PP # 22696. 26.3 NW " " NE " new area cor post fence W & S. 110.8 SE to NW cor large mach shed slope there. Corner line near line west side large maples north near toe slope road bed

#853406

Card # 3. 1/4 33-34 New Haven 10 8-15E (3)

11-9-1971. drove truck direct to spot found 5/8 x 18" rod and stakes set in 11-1970 .4' south and 5.3' west of CIM set. 10-1965 as described.

- pulled CIM and small rod set below.
- set CIM over 5/8"x18" rod at new corner location
- also mens from 1/16 shaft north on new section line. set 120 D 430' south of 1/16 shaft some 20' into wooded ravine 4'± east of blazed 8" pine as P.O.T. for line N.
- found mens to new CIM: 1306.87

W F Rarer 1897. 1308.12 J Kerr 1965 to old CIM 1306.5E

over

only reference to corner in open field.
325'± west to small elm in fence line.
215 ± 8'± east of due south 12"± elm in E W fence

Gov't Notes resting 1854
No. 01 set 1/4 post from which
White Oak 5 7/2 W 55 l
White Oak 18 in N 7/2 E 45 l

Nov. 1856 Thos. Hunter Pg 18 No. 30 shows 1/4 Post.
1/16 west 19.72 chs. M&L - B.T.'s (S 47½°W 16 lks.)(S 44 3/4°E 17½ lks.)
1/16 South 19.80 chs. M&L - B.T.'s (N 82°W 12 lks.)(S 50°W 59 lks.)