X 5/8" pipe inplace - fd by Vince Faugman 5-1982

#853605 (1)

section corner south 35-36 New Haven 108-15

North 1-2 Kalmar 107-15

2-1882 Hunter P373 No 364 S 35 C Gates, J Bryant. found stone in center road placed by Daniel Daly & other settlers where orig corner stood. Tested by Stamps & 2 witness trees - west 39.77 to fence south at S 1/4 35!

4-1919 C Armstrong P 302 B South line 36 Clare Sally. found stone and iron bolt as corner.

-16 east set stone 4x17x18 1316' N & L.

Now iron rod numerous ties, see S 1/4 36.

- Cemetery laid out from orig corner. has been tested.

- over -

Co Hwy Dept B 155 P6. 1948.

Iron pipe in black top as corner. P I Δ 0° 12' right.

Disc fence post NE 46.0 (45.65'

" spruce. N 37.0 (37.2.

Meas west. 2622.5

Center Grove Cemetery new layout. 1948 B 39 P 61

1" iron pipe 33' north of 35-36 then north 196.5 to NE corner plot a 1" pipe. - then west 172.5' 90°10' interior angle to 1" pipe then south 196.5 to 1" pipe 33' north of range line. lots 18 x 18 4' walks. - found section corner in road easily.

Co HD B 318 1966 found 3/4" pipe with box over it 265+85.38

Sp in pine ~~NE~~ gone 5-1982 40.41 - → Spike in pine N. 37.55' ~~39.94.~~

Sp in pine NW. 41.13' - Sp in PP L. 39.88 V.F.

Meas E 1315.18. R 1316.0 - Meas west 2622.10

Lawrence F. Set new Spike

Section corner Found 58-54 No Notes 108-15
North 1-2 Notes 107-15

#853605 (2)

50.00 Set post ------ to Orig. ---- 1-2-35-36

Black Oak 14 N 30° W 50
" " 10 N 9° E 67
" " 10 S 39½° E 69 54
Black Oak 14 S 83° W 37 50

5-1982 Vince Fangman called To report on this corner. He found 5/8" pipe inplace which he said he set over spike found when he worked for McGhie & Betts. He pulled pipe out and checked for (CIM ?) under it But found pipe to be about 18" long and over Something hard either CIM that deep or pipe is on top of Stone as above records indicate No CIM inplace. He checked Ties from 1966 Co. H.D. which are shown corrected in blue. RWB

32 "853605" D 5-15-98
mw EK

So 35-36 108-15 New Haven
N 1-2 107-15 Kalmar
(fd pipe) Set Rf pipe w/Cap
on South back slope of CR#14
ESE of Corner 44' South
of ℄ CR#14
ART P.K. in pp#(No. No.)(last
pole on North side CR#14
to S 35-36 108-15

216° 28' 16" dh04 217°04'30" dh02
0°48'14" dh02 1°24'32" dh00
215°40 02 215°39'58

To So 35-36 (pipe in ℄
CR#14 used by V.E. in Survey
VA 88° 22'00" dV00
slope 94.915 Hor 94.875

"853605" S SEC COR 35-36 108-15 6-7-99 EA JJ MAC MAR

FOUND PK NAIL SET BY SURVEY CREW, SET

1" SQ PIPE W/CAP @ SURFACE, CORNER FALLS

1' N OF ℄ CR 14 + 68' W OF CEMENTRY

DRIVEWAY NORTH.

CSD IN PP#23807 S 39.86'