/ 9-3-76 Set CIM #853606

(1)

1/4 Corner 35-36 New Haven 108-15.

2-1882. Hunter P 373 No 364 S 35 C Gates, J Bryant. Corner gone but Mr. Daniel Sally avers he set corner post in center mound. it being his NW corner. (No means.

9-3-76 Dug around corner post and around ½" rod found on N side of C.P. (Set by Doug Bate). Found the ½" rod to be driven in a ½" x 32" pipe with a horseshoe around it. Accepted this a corner. Set a CIM on a sash weight with horseshoe around the sash weight. Corner falls 60' S.W. of the ℄ of the State Trail (former railroad) taken at Rt ∠'s to track

R.P.'s Nail and CSD in N side Box elder NE 16.33
Nail and CSD in S. side Box elder ESE 16.01
Gov't Mons cut bear ~~tree~~ tree
40.00 set 1/4 sec post in mound
dug pits 95 ft. N 5 links dug
Charcoal 95 stakes

Jan, 1862 Samuel McDowell Pg. 67 No. 94 shows 1/4 Cor.
used to set Center 35, & broke down west 1/2 Sec. 35

1/4 35-36 New Haven 108-15 (2)
#853606

McGhie & Betts - 8-22-1967
Dug for old recorded post in mound but found nothing used existing Cor. post and 1/2" rod inside of 3/4" pipe at base existing post as 1/4 Corner - fences run South and West - Some fence To East.