3-2

Sec. 20-21-29

Drwg. No. 3-2

fd- Kerr's Bolt under Shattered Stone. Set CIM over Bolt

C.I.M. by Kerr
N 10537.80
E 2653.31

fd- Stone Set C.I.M.
N 7917.91
E 2.19

fd- CIM. set by Kerr

fd- part of limestone Set CIM over it

fd- Bottom part of Stone Set C.I.M over it
N 5285.91
E 00.00

Water

Set 1/4 Cor. C.I.M. over 1/2" rod
Corner Set by line from West and Line from North

Set 1/4" Shaft as Section Corner
N 5265.94
E 5280.46
Corner set by projecting line from East and Line from South.

fd- Stone 14.5' N. & 9.8' W.
N 5270.1
E 10536.3

fd- thin Limestone Set Bottom of Stone

Found W. Fraser stone Set C.I.M. over it.

1/4 Cor. 7908.86

10-8-1974 Set C.I.M. over 1/2" rod
N 2648.95
E 00.00
hole in Culv. by M&L.

fd- CIM
N (-13.12)
E 5306.49

C.I.M. found
N 00.00
E 00.00

S 1/4 Cor. 29
fd. C.I.M.

Section 21 — dug at Cor. 21 did not find stone

Scale 1" = 500'

Sections 20-21-29
Viola Township
May, 1974