Can't locate this
to Field book

N 10357.586
E 4724.292

10,365.65
4077.52

646.80

1090.446

10,247.684
5819.473

10,249.362
5819.690

POT on Sec Line

Move N. 1.68'

3273.217
90-32-14

S 89°27'46" E
2626.41

Straight Line

4.42' dist N-S

Straight Line 2639.27' 7 Straight Line 8 Quarter Sec. Corns.

S 89°33'38" E

S 252.8'
NW¼ to NE¼

Straight Line

Line of existing fences to be established by Surveyor. This will not be used for Subdivision purposes. This will not destroy J. Kerr's claim of ownership but will be on left hand side of fence. Witness Corner is now 4.42' S. of Sec. Line

New ¼ Cor. of Sec.

10,334.955
7350.598

10,332.21
7845.005

494.42

N 10 872.83

N 9589.843
E 7353.020

N 9589.84
E 7352.86

N 9600.48
E 7354.65

N 9600.185
E 7351.794

@ 2644.12 10,872.832
7351.493
2412.473 Inv S

@ 2470.30
1006.V.436
7351.411
2404.593 Inv S

2688.68 measured

26 M.V.A. Inv
N 0°04' E

Point of Intersection

Az. N 40°37'45" E
1504.2'

Az. 97°23'49"
1135.68

Az. 39°35'22"
1614.41

Az. 71°06'58"
2685.69

Az. 39°21'02"
2107.62

Az. 317°19'43"
2149.35

Az. 291°00'00"
1239.54

Az. 245°45'30"
1149.98

N 9443.811
E 8477.362

9443.795
8477.266

2626.12 Comp

1314.90

1322.48

1324.87

1314.90

1314.90

1324.87

1322.48

1314.90

1314.90

1324.87

1322.48

1314.90

1314.90

1324.87

1322.48