Feb 16 1978
In doing the corr. on the W 1/4 cor 7
I did more research in trying to establish
the procedure used by C. Larson in setting
the W 1/4 cor. He may have set it on the
total mile or on line + midway between
the two 1/16 corners. Because we feel
we have Both T. Hunter's S.W. 7 and the
1/16 cor S. of this 1/4 corner we reset
the W. 1/4 7 doubling the line and distance
T. Hunter had 19.81 and we now
have 1307.85. In the N 1/2 mile
T. Hunter had 2617.56 and
we now have 2623.70
which is hard to explain

Note! Bf error on
shot from "B" to SW Cor 7
Also problem in coord.
from Kastler's #1 to
Kastler's #2

Scale 1" = 400'

3-58A Rochester Twp
Sec. 7-106-14
Dwg. 3-58A

ZR2-4985
608 687-9202