Certificate of Location of Government Corner

ID#: 400608 **Description:** N 1/4 SEC 06 40 **Date Set:** 7/3/1985 **County:** Fillmore

Section: 06 **Township:** 104N **Range:** 10W **Monument Description:** Witness Monument - Cast Iron Monument

Reference Ties:

Corner History:

Corner was not set during the Public Land Survey

6-1894 O.H. Case, County Surveyor, set a stone at the corner during a survey of Section 6. Irving Bacon later found a stone at the corner.

1-1985 Doug Rude, of Yaggy Associates, searched the approximate area of the corner, but found a large erosion washout which had removed any evidence of the stone monument. He also searched for the bearing trees at the southwest corner of Section 31, Township 105 North, Range 10 West, which should lie 37 links east of the North Quarter corner. A 1" pipe was found at the southwest corner of the Northwest Quarter of the Northeast Quarter of Section 6, the pipe was set by Case in his 1894 survey and perpetuated by Bacon.

7-3-1985 Yaggy Associates, set a Fillmore County cast iron monument 40.00 feet west of the North Quarter corner on the north line of the Northwest Quarter of Section 6. The monument was set on an offset because the actual corner position falls on the side of the erosion washout. The actual position of the corner was set on a projection of the line from the South Quarter corner through the 1" iron pipe. The north-south position was established at prorated measure of the 1894 O.H. Case survey.