Certificate of Location of Government Corner

ID#:430108 **Description:** N 1/4 SEC COR 1 43 **Date Set:** 6/5/1981 **County:** Fillmore

Section: 01 **Township:** 104N **Range:** 13W **Monument Description:** 1" iron

Reference Ties:

The monument is down 0.4'
The corner falls in line with fence south and 3' north of centerline of E-W twp road.
This corner is located by GPS measurement.

Corner History:

This corner was not set during the Original Public Land Survey

Fillmore County survey records indicate a 4" x 13" x 15" limestone was set at the north quarter corner of Section 1-104-13. The name of the surveyar who set it and the date it was set are both unknown.

6-5-1981 Olmsted County Surveyor found three limestone pieces which measured 4"x13"x15" together 2' deep. Took them as corner. Placed two RR spikes on the north side and two on the south side of the stone. Set a 1"x30" iron at the road surface and over the stone.

3-7-1996 David Knutson, Fillmore County Surveyor, prepared a Certificate of Location which noted the 1981 work done by Olmsted County. The Certificate of Location was recorded with the Fillmore County Recorder as Doc. No. 374608 on 8-28-2009.

11-1-2010 Olmsted County survey crew found 1" iron down 0.1 bent and leaning.

5-27-2011 Olmsted County survey crew found 1" sq. pipe bent with the top mangled. Removed and cut off the damaged portion of the pipe. Reset pipe in the original hole