Certificate of Location of Government Corner

ID#:430606 **Description:** W 1/4 SEC COR 6 43 **Date Set:** 6/12/1995 **County:** Fillmore

Section: 06 **Township:** 104N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fence west, 5' east of fence south and 1 1/2' north of fence east
County Survey Disk in fence post W 6.60'
County Survey Disk in transmission PP SW 4.65'
Post w/sign 1/2' north
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: 40.0 set quarter section post and built mound and drove stake and planted osage orange seed in SE corner.

5-1902 W. Fraser Pg.16B; found old stake in center of mound. Drove iron stake in place of stake. 16 west set stone, 16 north set stone, and 16 center NE 1/4 set corner.

11-12-1971 Olmsted County Surveyor set 3/8"x4' rod as corner.

5-15-1995 Olmsted County Surveyor found 3/8" iron up 10" set in 1971 by County Surveyor in line of fence west, 1 1/2' north of fence east & ±5' east of fence south.

6-12-1995 Olmsted County Surveyor set CIC/square pipe at 3/8" rod location by Roger Brand, County Surveyor in 1971 at which time he ran the E-W 1/4 line of section 1 and doubled his 1/16 pipe to set the 3/8" rod. The corner falls in line of fence south & 1 1/2' north of fence east. RPs-CSD in fence post west 6.60', CSD in transmission PP SW 4.65', Sign and post 1/2' north.

7-3-2002 Olmsted County Surveyor found cast iron cap on telspar pipe up 0.2' in good condition.