Certificate of Location of Government Corner

ID#:440105 **Description:** SEC COR 1 2 11 12 44 **Date Set:** 6/12/2002 **County:** Olmsted

Section: 01 **Township:** 104N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4' west of fence north, 2' west of fence south and 5' south of centerline of CR 106
Concrete nail in 8" Pine SE 52.65'
Center 15" Pine SSE 41.6'
Bolt in top 8" square concrete post S 34.7'
This corner is located by GPS measurement

Corner History:

1902 W. Fraser (BK. B pg. 16) found the stake and stone in the center of the road in line with the N-S fences.

9-14-1971 Olmsted County Surveyor found a 6" by 7" by 14" limestone down 2.6'. Set CIM over iron over stone.

5-3-1995 Olmsted County Surveyor found CIM in good condition deep in E-W CR 106.

6-12-2002 Olmsted County Surveyor found CIM with head broken off. Removed broken CIM and limestone. Set 6' telspar pipe w/Cast Iron Cap.