Certificate of Location of Government Corner

ID#: 450508 **Description:** N 1/4 SEC COR 5 45 **Date Set:** 12/11/2012 **County:** Olmsted

Section: 05 **Township:** 104N **Range:** 15W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

Corner History:

6-14-1875 T. Hunter; In unrecored survey, set stake M & L (Field Book 4, Page 70-71)

6-1898 W.Fraser (Book A, Pg.633 No.572) Found old stake set by Hunter. Set boulder in place. N 1/4 5 set stake with boulder stone on each side.

1941 County Highway Department Bk.109 Pg74; Found boulder with chisel shaped top 1.5' north and 1' east of fence running south.

9-1-1993 County survey crew found and measured the location of a fence corner post.

10-14-2011 County survey crew searched for but did not find the boulder from 1941. Fence south is now gone.

12-5-2012 Olmsted County survey crew used a small backhoe to dig an area to cover both the fence corner post as was measured in 1993 and the boulder location. Dug to a depth of 4' and foud evidence of an old post mark but did not find a boulder or any other survey evidence.

12-11-2012 Olmsted County Survey staff computed a location midway between NW corner Section 5 and NE corner Section 5 and on line from S 1/4 corner 31-105-15 and south section corner 31-32. Corner location falls 1.4' north and 0.5' east of fence corner post as found in 1993. Set a 7' telspar pipe with cast iron cap at the computed location.