Certificate of Location of Government Corner

ID#:510106 **Description:** 1/4 SEC COR 1 2 51 **Date Set:** 9/23/1998 **County:** Olmsted

Section: 01 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 0.4'
The corner falls 1 1/2' south of main line of fence west and 35' west of pasture fence
This corner is located by GPS reference stations "Pieper I & II"

Corner History:

8-1853 Gov't notes N. 40 chains, thence 39.46 chains to section corner, set 1/4 section post, Burr Oak 8" N 43 W 21 links, Burr Oak 13" S 45 W 35 links.

11-1891 Thomas Fraser pg 462 no 446 found stone 1-1/2' SE old stone fence in place 30 years. Corner always there and undesputed. Measurement north 39.54' S 6' E. 1/16 west set stake.

4-1892 Thomas Fraser pg 476 no 455 found corner pg 462, no measurement, no 1/16.

5-1900 Robert Fraser pg 674 no 599 found stone at end of stone wall claimed by settlers and former surveys. 1/16 east drone stake, no description or measurement.

9-14-1998 County Surveyor dug for stone used by Fraser's in three surveys. Remnants of old stone fence still here, may use for final location. Found nothing further.

9-23-1998 County Surveyor set Cast Iron Cap on 3' long telspar pipe driven to refusal 1 1/2' Southeast of stone fence called for in previous surveys.

2-16-2011 County survey crew found cast iron cap on telspar pipe in good condition.