Certificate of Location of Government Corner

ID#:510506 **Description:** 1/4 SEC COR 5 6 51 **Date Set:** 7/29/2003 **County:** Olmsted

Section: 05 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 6' east of centerline of N-S twp road and in line with fence west
County Survey Disk in CP W 32.05'
County Survey Disk in PP #2065 SW 120.25'
Spike & disc in S side Maple cluster E 23.13'
This corner is located by GPS measurement

Corner History:

8-1853 Gov't Notes William A. Jones, Deputy Surveyor South on true line between sections 5 and 6. 40.11 chs. Set quarter section post. Burr Oak 10" N19ºE 454 lks. Dug trench. 80.00 chs. To section corner.

5-1875 Thomas Hunter (P. 278 No. 275), County Surveyor, found a mound with part of the old stake in the center. Set a 8"x10"x18" boulder.

7-13-1976 County Surveyor dug with the backhoe and found the recorded stone (top broken). Lowered the bottom portion of the stone and drove a 1/2" rod on the West side and a flat iron on the East side. Set a C.I.M. over all.

7-8-1996 County Surveyor found CIM in good shape 4" deep in crushed rock 150th Ave SE.

7-23-2003 County Surveyor found CIM down 0.3' in good condition.

7-29-2003 County Surveyor noticed CIM to be slightly leaning SE. Took local ties and removed CIM, 1/2" rod, & flat iron. Took ties to stone and removed. Set CIC on a 5' telspar pipe down 0.4' at stone location.