Certificate of Location of Government Corner

ID#:511104 **Description:** 1/4 SEC COR 11 14 51 **Date Set:** 9/8/1975 **County:** Olmsted

Section: 11 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument is down 0.4'
The corner falls in cultivated field
Post w/sign 1' north
This corner is located by GPS reference stations "South Shoulder & North Shoulder"

Corner History:

9-1853 Gov't Notes W.A. Jones, Deputy Surveyor West between sections 11 and 14. 39.971/2 chs. Set quarter section post. Deposited stone 18"x12"x2". Dug trench and pits and planted cherry seeds N.E. and S.W.

4-1892 Thomas Fraser (P. 477 No. 456), County Surveyor, states corner completely gone. Set temporary point midway.

9-8-1975 County Surveyor dug at midway and on line location but found nothing. Set C.I.M. over 1/2"x6" pipe midway and on line between Sec. Cor. 11-12-13-14 and Sec. Cor. 10-11-14-15.

9-18-1998 County Surveyor found CIM down 1.2' in good condition.

4-4-2006 GGG, Inc. found and used monument in section 11 survey.

10-26-2011 County survey crew found cast iron cap on telspar pipe