Certificate of Location of Government Corner

ID#:511106 **Description:** 1/4 SEC COR 10 11 51 **Date Set:** 11/17/1998 **County:** Olmsted

Section: 11 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 0.2'
The corner falls 150' west of east end of terrace
Post w/sign 1' south
This corner is located by GPS reference stations "Cravath II & III"

Corner History:

8-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 10 and 11. 40.00 chs. Set quarter section post. Burr Oak 8" S701/2E 122 lks. Burr Oak 5" S761/2W 95 lks.

4-1892 Thomas Fraser (P. 477 No. 456), County Surveyor, states corner gone for years-plowed out. Set stone 3"x8" / 12"x20" midway and on line. Set stone at 1/16 north. Set 2 stones 10"x20" at 1/16 south.

8-13-1975 County Surveyor dug in old fence line at 1/16 north and found 3"x10"x24" vertical limestone 11/2' deep.

8-14-1975 County Surveyor dug at 1/16 south and found 2 stones 2"x10"x20" 2' deep and 1' north of the E-W fence.

8-14-1975 County Surveyor dug 6'x6' to clay at corner location but found nothing.

8-19-1975 County Surveyor set C.I.M. (down 14") over 3/4"x23" rod as corner in open field at 2/3 the distance and on line from Sec. Cor. 2-3-10-11 to the 1/16th south of 1/4 Cor. 10-11.

11-17-1998 County Surveyor found CIM set in 1975 now 3.2' deep in terrace built on contour. Set Cast Iron Cap on telspar pipe over CIM over 3/4" iron.

2-15-2011 County survey crew cast iron cap on telspar pipe in good condition