Certificate of Location of Government Corner

ID#:511405 **Description:** SEC COR 14 15 22 23 51 **Date Set:** 12/9/2004 **County:** Olmsted

Section: 14 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' south of centerline of CR 110, in line with fence north and 2 1/2' east of centerline of middle farm driveway south
County Survey Disk in PP NW 60.34'
This corner is located by GPS reference stations "Urban A & B"

Corner History:

Gov't notes: set post and stone 14x10x3", mound & pits.

6-1873 Hunter pg 230 no 233 sec 22-23 found mound and 2 slight pit impressions and remains of old stake in center mound. Set stone 3x4x18". 1/16 E - set deep stake 1/16 S - set temporary stake 1/16 W - set stone 2x10x16"

4-1878 Hunter pg 339 no 333 sec 15 found stone described pg 230. 1/16 W - set stone 2x5x23" 1/16 N - set temporary point

8-1989 County Surveyor dug with backhoe at corner location to clean clay and found nothing. Also dug at the 1/16 corner W and found nothing.

10-11-2002 County Surveyor set 2 points to GPS to determine location of section corner.

12-9-2004 County Surveyor set 5 1/2' telspar pipe w/cast iron cap down 0.4' at computed position from GPS and traverse data.