Certificate of Location of Government Corner

ID#:511506 **Description:** 1/4 SEC COR 15 16 51 **Date Set:** 10/25/1983 **County:** Olmsted

Section: 15 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls under wire gate leading into large cattle pasture
County Survey Disk in S side gate post W 15.35'
County Survey Disk in S side gate post E 14.05'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: William A. Jones Deputy Surveyor North between Sections 15 and 16. 40.00 chs . Set quarter section post. Deposited stone 28in. x 4 x 6. Made mound and dug trench and pits. Planted cherry seeds N.E. and S.W.

4-23-1878 Thomas Hunter, County Surveyor, (Book A, Page 339, No.333) found stone planted in center of road, claimed by Mr. William Gardner to be set by a surveyor in mound where the original 1/4-post stood." Hunter used the corner to set the Center 15, a 26x4x3 inch stone, at intersecting 1/4-lines. He also set the 1/16 East of the Center 15, a temporary stake, midway (20.04 chs.) and on line to the E. 1/4-Cor. 15, a boulder set in place of stake found.

10-25-1983 County Surveyor dug for the corner in line with the fence West and in line with the center of the old road running South (center of the road North no longer distinguishable). Found a 3"x8"x12" limestone dug in and standing perfectly. The top of the stone was 3' deep and right at the level of the remaining natural ground and could have been broken of by road construction. Found a mark beneath the stone that could be a stake mark but there was no wood pieces remaining. Moved the stone .55 West to make room for a telspar pipe with a cast iron cap for the corner. Put pieces of cast iron around the stone.

10-11-2002 County Surveyor found telspar with CIC down 2.3' in good condition. Monument falls underneath gate/fence leading into large cattle pasture. CSD in South side of gate post 15.35' West and CSD in South side of gate post 14.05' East.