Certificate of Location of Government Corner

ID#:511705 **Description:** SEC COR 17 18 19 20 51 **Date Set:** 2/22/2007 **County:** Olmsted

Section: 17 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

County Survey Disk in S side of PP SE 1.98'
Sign on PP 2' east
This corner is located by GPS measurement

Corner History:

8-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 19 and 20. 80.00 chs. Set post-corner to sections 17,18,19&20 Burr Oak 7 in. S83ºW 566 lks. Burr Oak 6 in. N85ºW 591 lks.

6-1899 William Fraser (P. 585), County Surveyor, found a 11/2"x10"x16" stone with a stake on the South side and small stones on the West and South sides of the stake. Took a bearing tree: 4" Burr Oak N40ºE 2 lks.

6-16-1976 County Surveyor found the recorded stone broken in two pieces with small limestones piled around. Also found the stump of Will Fraser's bearing tree now used as the corner post to fences N-S-E. Set a C.I.M. over a 1/2" rod as the corner. Set one piece of the stone on the North side and the other piece on the South side of the C.I.M.

12-3-1987 County Surveyor found CIM in good condition.

2-22-2007 County Surveyor found CIM down 0.1' leaning north, took local ties and removed. Found 1/2" iron rod down 2', ties showed CIM leaning slightly north, took local ties and removed. Set 5 1/2' telspar pipe w/CIC from local ties taken from CIM. CSD in S side of PP no # SE 1.98'. Nailed sign on PP to the east.