Certificate of Location of Government Corner

ID#:511804 **Description:** 1/4 SEC COR 18 19 51 **Date Set:** 12/18/1987 **County:** Olmsted

Section: 18 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 0.3'
The corner falls 2' south of CP to fences E-W-S
County Survey Disk in CP N 2.55'
County Survey Disk in NW side Red Oak NE 7.95'
This corner is located by GPS measurement

Corner History:

Gov't notes: set 1/4-sec-post 40chs - dug trench 12" Burr Oak, W 235 lks

5-17-1875 T. Hunter pg 276 no 273 18 found remains of old stake by fence corner post. Placed stone 4x7x13" in its place.
1/16 W - set granite stone 6x6x18"

9-30-1976 County Surveyor found stone as described by Hunter lying flat on SW side of corner post to fences E-W-S. Straightened stone where bottom came. 1/16 W - stone found.

12-10-1987 County Surveyor found nothing. Probed and found stone 4x7x13" lying flat +/-2' NW of CP to fence E-W-N .

12-18-1987 County Surveyor set cast iron cap on telspar pipe at intersection of N-S-1/4-line of sec 18 and on line from West section corner 18-19 over Thomas Hunter 1/16 corner.

3-25-2011 County survey crew found cast iron cap on telspar pipe in good condition